



Your Ref : D20002401MFSH

Date: 08th July 2020

Our Ref : CS4/FCI20006234/Ntqs2

M/s MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHC 960T
ACCIDENT ON 08.06.2020**

Instruction was received to inspect the vehicle Reg. No. SHC 960T. The inspection was conducted on 12/06/2020 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHC 960T
Make/Model	: Mercedes Benz Viano 2.2 CDI
Year of Registration	: 2013
Body Colour	: White
Chassis Number	: WDF63981323803007
Engine Capacity	: 2143 cc
Speedometer Reading	: Battery Melted

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$92,017.67 (Sin Dollars: Ninety-Two Thousand Seventeen and Sixty-Seven Cents only.) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Book Value	S\$ 47,933.00	
<i>Less:</i> LTA Reimbursement Value (RV)	(S\$ 43,986.00)	
	<hr/>	
Nett Liability	S\$ 3,947.00	
		S\$ 3,947.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)	S\$ 92,017.67	
	<hr/>	
Nett Liability		S\$ 92,017.67
(a) – (b) =		<hr/> (S\$ 88,070.67) <hr/> =====

The amount of estimated saving of S\$88,070.67 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.