

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 08 Jul 2020

Preliminary Advice

Vehicle No	: SMT1725B	Accident Date	: 11/05/2020
Make	: AUDI Q3	Policy No.	: 2070058594
Assignment Date	: 10/06/2020	Excess	: S\$800.00
Date of Inspection	: 09/06/2020	Est. Duration of Repair	: 15 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,047.00
Revised Amount	:S\$	19,376.00
Check Items (Estimated)	:S\$	400.00
Total	:S\$	19,776.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	143,000.00
COE / PARF Rebate	:S\$	55,012.00
Salvage Value	:S\$	
Margin for Repair	:S\$	87,988.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 1,293.00.