

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

08, JUNE 2020

India Int'L Ins PL
64 Cecil Street #04-05/
IOB Building S 049711

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SHA7221H
Accident involving vehicle no: SJR568R/SHA7221H
DOA: 05/06/2020 AT Third Hospital Ave (SGH)

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SJR568R
To supply—

Description	Qty	Amount
Rear bumper	1	660.90 X
Rear bumper retainer	1	166.90 X
Rear bumper reflector	1	82.33 X
Rear fender, Rh	1	1,161.80 X
Parts		2,071.93
Parts less 25%		517.98
		1,553.95

To remove/reinstall fender glass
To remove damaged parts n attachments
Cut n weld damaged panel
Replace/align all parts into position
To spray paint

~ 150.00 X

950.00 1000
600.00 300

3,253.95

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: