

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 11 Jun 2020

Preliminary Advice

Insured Vehicle No	: GBF5034P	Accident Date	: 08/06/2020
TP Vehicle No	: SMM6539B	Assignment Date	: 09/06/2020
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 8
Date of Inspection	: 9/6/2020		
Inspection At	: Team Autopro Pte Ltd		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion, n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,894.45
Revised Amount	:S\$	10,247.98
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,247.98

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a 'Without Prejudice' basis