CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVE 6 #01-39 AUTOBAY SPORE 417883

VEHICLE No: GBG 4687G

1PC	FRONT BUMPER 1250	De/701 \$1,480.00
1PC	FRONT BUMPER SIDE RETAINER N/S 66-57	C/19 \$88.50
1SET	FRONT BUMPER CLIPS	The \$50.00
1PC	FRONT BUMPER FOG LAMP N/S 425.00	CNO \$685.00
1PC	FRONT BUMPER REINFORCEMENT	1 1 \$699.00 ×
1PC	HEADLAMP N/S /150.00	C Ne \$1,820.30
1PC	FRONT SUPPORT PANEL	\$945.20 X
1PC	FRONT FENDER N/S 628.00	PD/3ert \$921.30
1PC	FRONT FENDER INNER SHIELD N/S 226-20	70-7 \$295.40
1SET	FRONT FENDER INNER SHIELD CLIPS N/S	Nel \$50.00
1PC	WIPER WASHER TANK 245.00	\$288.00
1PC	FRONT SHOCK ABSORBER N/S	イイ \$750.00 メ
1PC	FRONT TOP ARM N/S 311-50	TWI \$615.00
1PC	FRONT LOWER ARM N/S 699-30	Berf \$1,022.00
1PC	FRONT KNUCKLE ARM N/S 788-20	1 Sent \$945.00
1PC	FRONT KNUCKLE ARM BEARING N/S	Nel \$450.00
1PC	FRONT TIE ROD END N/S 182.00	(106 TNI- \$215.00)
1PC	FRONT STEEL RIM N/S	Bent \$150.00 50 5.2
		\$11,469.70

Not Authorised Alele 9/6/20 2/5 \$ 5800 Hdays.

TO CHECK WIRING		\$50.00 20
TO SPRAY RUST PROOFING		\$80.00 30
TO CONDUCT WHEEL ALIGNMENT		\$120.00 &0
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE		\$180.00 120
TO REFILL AIR CON GAS		^^ \$120.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$800.00 450
TO PUTTY & SPRAY PAINTING		\$1,200.00 600
	TOTAL	\$14,019.70

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u>
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

nato

7-65815 104 5.923.35 143.35 5818