



Your Ref : SNM20D202078/C01/TAYHP

Date: 19<sup>th</sup> Jun 2020

Our Ref : CS/CTI20006265/Ksf3e2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBD 8155P  
ACCIDENT ON 29/01/2020**

Instruction was received to inspect the vehicle Reg. No. GBD 8155P. The inspection was conducted on 10/06/2020 at the premises of M/s 10 Ang Mo Kio Ind Park 2A #01-04 Ang Mo Kio Autopoint, Repairer : Cheng Hoe Motor Pte Ltd.

The following vehicle information was recorded:

Registration Number	: GBD 8155P
Make/Model	: Nissan Cabstar 3.0 5M/T ABS 2DR 2WD EURO 5
Year of Registration	: 2015
Body Colour	: White
Chassis Number	: JN1SC2F24Z0856752
Engine Capacity	: 2953 cc

The vehicle sustained damages at the front o/s portion and n/s body. The undercarriage and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 31,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 20,225.00 )
Nett Liability	<u>S\$ 10,775.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG  
*Licensed Appraiser*



K.K.LAU  
*MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.