

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 36610

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0413/2020/NS
Date : 8-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

14 days exclude 2 Sundays - ok

jb 7 Aug 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Woon Voon Ching
Address : 12 Tampines St 73
#13-04
Singapore 528828
Telephone : HP +65 83996893
Type of Claim : Own Damage Claim
Policy No. : 1800072803
Vehicle No : **SMA 9045 C**
Model Code : Audi A3 1.0 TFSI 8V
Model / Year : Jun-18
Engine No : CHZ 442513
Chassis No : WAUZZZ8V9J1059509
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jun-20
Place of Accident : Drive way to Yishun Community Hospital Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 9045 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	\$ 280.00
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	\$ 600.00
3	To install solar film for rear windscreen and 1/4 glass.	S/N \$	400.00	\$ 400.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 1,400.00
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	\$ 1,400.00
SUB TOTAL LABOUR CHARGES		:	\$ 4,080.00	\$ 4,080.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 9045 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
		<i>c/f</i>		\$ 4,080.00
6	To remove and transfer lhs rear door and lhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00	\$ 560.00
7	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$	350.00	
8	To dismantle rear bumper, rear lid, lhs rear door and lhs front door. Cut out and weld lhs rear fender. To renew lhs rear door and lhs front door. Re-organise crash management components. Reinstall all parts removed.	\$	7,000.00	\$ 4,000.00
9	To respray lhs rear fender, lhs rear door, lhs front door, door handle, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	5,950.00	\$ 3,125.00
10	Added labour charge	\$	300.00	\$ 150.00
11	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 18,432.00	\$ 12,107.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 9045 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	SECTIONAL PART - SIDE PANEL - LH	\$ 2,195.00	\$ 1,756.00
2	REAR WINDSCREEN	\$ 766.00	\$ 612.80
3	SIDE WINDOW - LH	\$ 537.00	\$ 429.60
4	PRIMER	\$ 19.00	\$ 15.20
5	FRONT DOOR - LH	\$ 2,375.00	\$ 1,900.00
6	FRONT DOOR OUTER SEAL	NEC \$ 151.00	\$ 120.80
7	BONDING AGENT	NEC \$ 46.00	\$ 36.80
8	CLEANING SOLUTION	NEC \$ 64.00	\$ 51.20
9	FRONT DOOR ATTACHMENT PARTS	\$ 121.00	
10	FRONT DOOR CATCH	\$ 89.00	
11	DOOR HINGE HAL-UPPER PART - LH UPPER	\$ 75.00	
12	DOOR HINGE HALF-LOWER PART - LH UPPER	\$ 45.00	
13	DOOR HINGE HALF-UPPER PART - LH LOWER	\$ 45.00	
14	DOOR HINGE HALF-LOWER PART - LH LOWER	\$ 75.00	
15	REAR DOOR - LH	\$ 2,375.00	\$ 1,900.00
16	REAR DOOR OUTER SEAL - LH	NEC \$ 151.00	\$ 120.80
17	BONDING AGENT	NEC \$ 46.00	\$ 36.80
18	CLEANING SOLUTION	NEC \$ 64.00	\$ 51.20
19	DOOR ATTACHMENT PARTS	\$ 227.00	
20	REAR DOOR CATCH	\$ 99.00	\$ 79.20
SUB TOTAL SPARE PARTS CHARGES		: \$ 9,565.00	\$ 7,110.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 9045 C

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 7,110.40
21	WHEEL HOUSING LINER		\$ 226.00	
22	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 84.00	
23	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
24	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
25	STONE CHIP	S/N	\$ 180.00	\$ 180.00
26	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
27	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
28	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
29	Added parts		\$ 952.00	\$ 761.60
30	SUNDRIES		\$ 400.00	\$ 81.92
TOTAL SPARE PARTS CHARGES			: \$ 12,307.00	\$ 9,033.92
TOTAL LABOUR CHARGES			: \$ 18,432.00	\$ 12,107.00
GRAND TOTAL			: \$ 30,739.00	\$ 21,140.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0413/2020/NS 10-Jun-20 Glory Tan 1 of 1 SMA 9045 C Audi A3 1.0 TFSI 8V	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	Wing mirror mounting LHS	\$ 952.00	\$ 761.60	
<u>Labours</u> 1	To respray lhs wing mirror cover.	\$ 300.00	\$ 150.00	
TOTAL		\$ 1,252.00	\$ 911.60	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant