LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 12 Jun 2020

Preliminary Advice

Insured Vehicle No : GBD8829D

TP Vehicle No : SGX4165Y Accident Date : 08/06/2020

Make : TOYOTA WISH Assignment Date : 10/06/2020

Date of Inspection : 10/06/2020 Est. Duration of Repair : 10.00

Inspection At : MY CAR CONSULTANT PTE LTD - UBI (HQ)

53 UBI AVE 1, #01-33 PAYA UBI INDUSTRIÁL PARK

SINGAPORE 408934

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,746.83
Revised Amount	:S\$	7,432.90
Check Items (Estimated)	:S\$	4,088.35
Total	:S\$	11,521.25

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

(

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP