

Our Job Ref No : 305403770Date : 10/06/20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : TAUFGIH: SHA7348B08/06/20


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: NTUC SGX194Y
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$1,198.79</u> |
| (b) Labour Charges | <u>\$1,100.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$2,298.79</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs:
- 3
- working days.

- 4.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : CHIANGTel : 62148314Fax : 65468156Signature : Name : TAUFGIHDate : 12/6/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 10.06.2020

Time: 14:45:46

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305403770
 REGN NO : SHA7348B
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4A)
 DATE OF REGN : 13.12.2019
 DATE/TIME IN : 09.06.2020 08:10
 ACCIDENT DATE : 08.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2712-G	PRIG4Q8 COVER REAR BUMPER	1	458.60	25.00	343.95
0002	04-01-0302-2713-G	PRIG4Q8 GUARD REAR BUMPER	1	552.60	25.00	414.45
0003	04-01-0302-2714-G	PRIG4Q8 RETAINER REAR BUM	1	112.70	25.00	84.52
0004	04-01-0302-2715-G	PRIG4Q8 COVER RR BUMPER -	1	82.70	25.00	62.02
0005	04-01-0302-2723-G	PRIG4Q8 REFLECTOR ASSY RH	1	142.00	25.00	106.50
0006	04-01-0302-2267-G	PRIVC BUMPER PIECE	10	25.00	25.00	18.75
0007	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.40	25.00	39.30
0008	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.40	25.00	39.30
0009	28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1	30.00	10.00	27.00
0010	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1	30.00	10.00	27.00
0011	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1	40.00	10.00	36.00

SUB-TOTAL : 1,198.79

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 10.06.2020

Time: 14:46:26

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305403770
REGN NO : SHA7348B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 13.12.2019
DATE/TIME IN : 09.06.2020 08:1
ACCIDENT DATE : 08.06.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING			640.00		
0001 SP	SPRAYPAINT CHARGE			400.00		
0002 17-01	CHECK ALL LIGHTING			30.00		
0003 20-22	REMOVE/REFIX REVERSE SENSOR			30.00		
				SUB-TOTAL	:	1,100.00
				TOTAL	:	2,298.79

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :