

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 12 Jun 2020

## **Preliminary Advice**

Insured Vehicle No	: YQ849H		
TP Vehicle No	: GBK2141G	Accident Date	: 09/06/2020
Make	: HONDA ACCORD	Assignment Date	: 10/06/2020
Date of Inspection	: 10/06/2020	Est. Duration of Repair	: 10.00
Inspection At	: EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ) 56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages O/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,773.65
Revised Amount	:S\$	2,750.00
Check Items (Estimated)	:S\$	1,161.75
Total	:S\$	3,911.75

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : SURVEY ON "WP"