

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

20-05-9236

Date:

18/5/2020

INVOICE NO.

9236

**Benefit Auto** 

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Registration No.

**SLH2383Y** 

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 528.00
		Total amount	\$ 528.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms) Principal Consultant



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference:

20-05-9236

Date:

18/5/2020

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Dear Sirs

RE:

Road Traffic Accident on 13/4/2020

**Benefit Auto** 

In accordance with your instructions received in this office on

4/5/2020

, we made arrangements to

examine the vehicle on

4/5/2020

at above-mentioned address. The following data was

recorded:

#### Vehicle details

Make	Honda	Registration	SLH2383Y
Model	Vezel	Chassis	RU31205223
Colour	Red	Gearbox	Auto
Odometer	257894km	Paintwork	Good
Steering	Good	Brakes	Good
Condition	Good		·

### Tyre Depths

Front left	235/50ZR18	85% Habilead
Front right	235/50ZR18	85% Habilead
Rear left	235/50ZR18	85% Habilead
Rear right	235/50ZR18	85% Habilead

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,000.00 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

### Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
   Impact Analysis Academy Pte Ltd
   IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171** 

Our reference

20-05-9236

Date

18/5/2020

Page

2

## Section A: Damaged Parts Assessment

Section	A. Damagea	raits Assessine	110		
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items:				7	
Front door lh	1	crushed	1125.80	1125.80	<b>✓</b>
Front door inner lock lh	1	damaged	298.40	298.40	✓
Front door weatherstrip Ih	1	ripped	201.00	201.00	× svc
Front door inner board Ih	1	deformed	485.70	485.70	<b>✓</b>
Front door window gear regulator Ih	1	bent/malfunction	233.00	233.00	<b>✓</b>
Front door window gear motor Ih	1	ceased	215.00	215.00	× svc
Front door glass outer moulding Ih	1	necessary	122.00	122.00	$\times$ SVC
Front door hinges @\$65.80 lh	2	bent	131.60	131.60	× svc
Front fender Ih	1	repair.respray	598.20	0.00	
Front fender outer protector Ih	1	cut	144.00	144.00	× svc
Front side mirror casing Ih	1	cut	198.12	198.12	X Repair
Side skirt lh	1	cut/graced	552.30	552.30	<b>/</b>
Centre door pillar lh	1	repair	378.90	0.00	
	Sub- Tota	ıl costs	4684.02	3706.92	2695.20
Perce	entage discount :	20%	936.80	741.38	-20%
	Sub-Total cost	ts for parts =	3747.22	2965.54	2156.16
Special Nett Items:					
Front fender protector clips Ih	set	necessary	20.00	20.00	× svc
Side skirt clips lh	set	necessary	40.00	40.00	30 🗸
	Sub-Total cost	s for parts	60.00	60.00	
			1		30
Parts Repair					
*	*	* _	0.00	0.00	
	Sub- Tota	l costs	0.00	0.00	
	Total costs f	or parts	3807.22	3025.54	

### Subsidiaries of Impact Analysis Consultant:

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

 <sup>■</sup> IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd www.iaconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference

20-05-9236

Date

18/5/2020

Page

3

### Section B: Labour Cost Calculation

	Но	urly rate	Manhr. Req.	Total		
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	48.00	15	\$	720.00	600 ✓
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.		Sub-contract work.		\$	800.00	600 ∨
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	30.00	<b>/</b>	
Transfer of existing front door mechanism to new door lh	\$	48.00	1.8	\$	86.40	80 🗸
Wiring and bulb checking	\$	48.00	0	\$		
		Total la	bour cost	\$	1,636.40	1

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

1310

P - 2156.16 N - 30L - 1310 3496.16

L/S - 2796.92 = 2800

5 repair days

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171** 

Our reference

20-05-9236

Date

18/5/2020

# **Section C: Summary Table of Total Repair Cost**

Description  Damaged Parts  Assessment (See section A)		Cost	
		\$3,025.54	
Further discount	20%	\$605.11	
Recommended cost of parts		\$2,420.43	(1)
1	ection B)	\$1,636.40	(2)
Total Repair Cost (Round off to hundred)		\$4,000.00	(1) + (2)

We would recommend a sum of	\$4,000.00	and	6	working days for repair.
No further items will be approved w	vithout our expresse	ed written agreeme	ent. Any sigr	
items will be subject to a supplemen				

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
   Impact Analysis Academy Pte Ltd
   IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com























































































