

REPAIR ESTIMATE

VEHICLE NO: SH 7132P

16.06.20

MAKE :

MODEL: PAULS G4

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT DOOR PANEL RH			\$1,797.20
1	REAR DOOR PANEL RH			\$1,789.90
1	RHS ROCKER PANEL			\$1,799.60
1	RH WHEEL COVER			\$346.40
	SUB TOTAL			\$5,733.10
	25.00%			\$1,433.27
	DISCOUNTED TOTAL			\$4,299.82
1	FRT DOOR COMFORT LOGO			\$75.00
1	REAR DOOR COMFORT APP			\$80.00
				\$155.00
	Labour Charge			\$760.00
	Panel Beating			\$600.00
	Spray Painting Charge			\$60.00
	Transfer door part to new door			\$200.00
	Tuff coat			\$120.00
	TOTAL LABOUR			\$1,740.00
	ESTIMATE TOTAL			\$6,194.82
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Taufik 97495749

WP

16/6/20 @ 335pm

Impsun

Resurvey after repair

Taufik @ lkhauto.com

03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: