

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH6078U

DATE: 17. Jun. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 16. Jun. 2020

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover			\$1,052.20 de -
1	Front Bumper Side Bracket - LH			\$24.60 x
1	Front Bumper Top Bracket - LH			\$22.40 x
10	Front Bumper Clips		\$2.20	\$22.00 ncc ✓
1	Front Bumper Grille - LH			\$93.60 x
1	Headlamp Support Panel			\$907.40 x
1	Front Fender - LH			\$663.00 x
1	Front Fender Shield - LH			\$174.90 x
1	Headlamp - LH			\$1,388.00 x
SUB TOTAL				\$4,348.10
LESS 20%				\$869.62
DISCOUNTED TOTAL				\$3,478.48
1	Advertisement - LHF Fender			x \$100.00 Nett
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				\$100.00
Labour Charge				
1	Panel Beating			\$600.00 280
1	Spray Painting Charge			\$500.00 200
1	Tuff Kote			\$80.00 x
1	Wiring Charge			\$80.00 x
TOTAL LABOUR				\$1,260.00
ESTIMATE TOTAL				\$4,838.48
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfiki 97495749
 WP
 Insurance
 Resurvey after repair
 02 days.
 tanfiki@kianato.com
 17/6/20 @ 345pm.

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 119071

Mainline - 65 6363 6280 Facsimile - 65 6290 8755

Workshops

59 Loyang Drive Singapore 508969

24 Sennok Loop Singapore 758156

381 Sin Ming Drive Singapore 575717

11 Surge Road Way Singapore 728191

45 Panvar Road Singapore 705785

501 Vishnu Industrial Park A Singapore 768733

A member of COMFORTDELGRO

Date/Time: 16.06.2020 17:45

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305405384

STOMER

COMFORT TRANSPORTATION PTE LTD

AMS 7010045

STOMER NO 383 SIN MING DRIVE

DRESS Singapore SINGAPORE 575717

65508755

(R) (O)

(P)

ACCOUNT CARD NO.

VARS

REGN NO: SH 6078U

MILEAGE

MAKE: HYUNDAI

FUEL

MODEL I-40

DATE/TIME IN 16.06.2020 13:25

YR OF MANU 03.09.2015

TARGET DATE

CHASSIS CODE KMHLB41UMGU077212

COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 16.06.2020


NATURE: 3P 16.06.2020

S/NO

LABOR CODE

DESCRIPTION

AIG - Left Front



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedgeprint Slip

Exit Pass

Vehicle No: SH 6078U

LARRY

Vehicle No: SH 6078U

Larry Ng

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard