


張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-E
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

India International Insurance
64 Cecil Street
#04 -05 IOB Building
Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

Dear Sir/Madam

RE: THIRD PARTY CLAIMS FOR FBP1019H AGAINST YOUR
INSURED SMA6007H, ACCIDENT ON 23.01.2020 AT ALONG
SELETAR EXPRESSWAY



2 Days.
part by part.
After repair photos
Guo Qiang
UKK
8288 0282
18/6/2020

PG 1

DESCRIPTION	AMOUNT
1 TOP FRONT CENTRAL COVER ✓ BR	\$ 90.00
2 UNDERBRACKET ?	\$ 240.00
3 STEERING CONE ?	\$ 90.00
4 HANDLE BAR ?	\$ 64.00
5 BRAKE LEVER RH ?	\$ 24.00
6 METER COVER ✓ CMA	\$ 60.00
7 MUFFLER COVER ✓ Ct.	\$ 50.00
8 SIDE COVER RH (2 X \$70) ✓ Ct.	\$ 140.00
9 INNER COVER ✓ CMA	\$ 50.00
10 MIRROR BRACKET ✓ BT	\$ 14.00
11 LOWER HEADLAMP CENTRE COVER ?	\$ 76.00
12 LOWER COVER RH ?	\$ 50.00
13 SIGNAL LIGHT RH ✓ CMA	\$ 38.00
14 HEAD LAMP ✓ CMA	\$ 320.00
15 HEAD LAMP BRACKET ?	\$ 40.00
16 SIDE REAR LAMP ✓ Ser	\$ 50.00
	<u>\$ 1,396.00</u>
Less 10%	\$ 139.60
Sub Total	<u>\$ 1,256.40</u>
Nett Item	
1 TRANSPORT	\$ 60.00 30
2 LABOUR CHARGES	\$ 220.00 180
Sub Total	<u>\$ 280.00</u>
Total	<u>\$ 1,536.40</u>

THANKS
TSP