

## Denise Tay (LKKAUTO)

---

**From:** Rasul (LKKAUTO)  
**Sent:** Wednesday, 29 July 2020 12:56 PM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** FW: DIRECT SETTLEMENT FINAL REPORT-SKV341U  
**Attachments:** SKV 341U(1).png; SKV 341U(2).png; SKV 341U(3).png

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Hi Denise,

finalised

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Rasul (LKKAUTO)  
**Sent:** Wednesday, 29 July, 2020 12:52 PM  
**To:** Mohamad Bin Mohd Sanif  
**Subject:** RE: DIRECT SETTLEMENT FINAL REPORT-SKV341U

Hi Mohamad,

Noted thanks

Repair limit of 18K is confirmed

Wa'alaikumussalam

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Mohamad Bin Mohd Sanif [<mailto:mohd.sanif@simedarby.com.sg>]

**Sent:** Wednesday, 29 July, 2020 12:05 PM

**To:** Rasul (LKKAuto)

**Cc:** Toh Jing Xuan; Teng Wai Khan; Keith Leo Chi Yung; Cresendo Llorca Lagman; Bernard Wan Chong Huat; Inthiran Thurasamy

**Subject:** RE: DIRECT SETTLEMENT FINAL REPORT-SKV341U

Hei Rasul,

I believe my friend Mr Akbar had contact you regards to the bulb issue. He had explain about the bulb which is inside the tail len.

Hope this could clarify your enquiry so that we could settle the final report. if there is doubt you could contact me.

Thank you. Assalam mulaikum.

Best regard,

Mohd.Sanif  
Bodyshop

BMW  
Performance Motors

DDI: +65 6319 0148

FAX: +65 6474 3229

Address : 303 Alexandra Road, Singapore 159941

Email: [mohd.sanif@simedarby.com.sg](mailto:mohd.sanif@simedarby.com.sg)

[www.bmw.com.sg](http://www.bmw.com.sg)

**Sime Darby Motors**  
**A member of the Sime Darby Group**



---

**From:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>

**Sent:** Wednesday, July 29, 2020 10:34 AM

**To:** Mohamad Bin Mohd Sanif <[mohd.sanif@simedarby.com.sg](mailto:mohd.sanif@simedarby.com.sg)>

**Cc:** Toh Jing Xuan <[toh.jing.xuan@simedarby.com.sg](mailto:toh.jing.xuan@simedarby.com.sg)>; Teng Wai Khan <[teng.wai.khan@simedarby.com.sg](mailto:teng.wai.khan@simedarby.com.sg)>; Keith Leo Chi Yung <[keith.leo.chiyung@simedarby.com.sg](mailto:keith.leo.chiyung@simedarby.com.sg)>; Cresendo Llorca Lagman <[cresendo.lagman@simedarby.com.sg](mailto:cresendo.lagman@simedarby.com.sg)>; Bernard Wan Chong Huat <[bernard.wan@simedarby.com.sg](mailto:bernard.wan@simedarby.com.sg)>; Inthiran Thurasamy <[inthiran.thurasamy@simedarby.com.sg](mailto:inthiran.thurasamy@simedarby.com.sg)>

**Subject:** RE: DIRECT SETTLEMENT FINAL REPORT-SKV341U

[External Mail] This email originated from outside of the organisation; be careful with requests, attachments and links.

Hi Mohamad,

Under the final report there are 2 item listed that is NUMBER PLATE LED LIGHT. Is the other item is it supplementary?

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Mohamad Bin Mohd Sanif [<mailto:mohd.sanif@simedarby.com.sg>]

**Sent:** Tuesday, 28 July, 2020 1:03 PM

**To:** Rasul (LKKAuto)

**Cc:** Toh Jing Xuan; Teng Wai Khan; Keith Leo Chi Yung; Cresendo Llorca Lagman; Bernard Wan Chong Huat; Inthiran Thurasamy

**Subject:** DIRECT SETTLEMENT FINAL REPORT-SKV341U

Dear Rasul,

For Your Perusal:

Labour	\$16,830.00
Parts	\$8,256.79
Total	\$25,086.79

Note: Original was given 20 working days.

Owner to Claim CAR RENTAL=\$1600.00

LTA FEE=\$7.45

LIMIT REPAIR \$18,000.00

Best regard,

Mohd.Sanif

Bodyshop

BMW

Performance Motors

DDI: +65 6319 0148

FAX: +65 6474 3229

Address : 303 Alexandra Road, Singapore 159941

Email: [mohd.sanif@simedarby.com.sg](mailto:mohd.sanif@simedarby.com.sg)

[www.bmw.com.sg](http://www.bmw.com.sg)

**Sime Darby Motors**

**A member of the Sime Darby Group**



“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”