

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX155B
YEOH KAH HENG
BLK 41A BEDOK RIA CRESCENT
02-45
SINGAPORE 489929
TEL : FAX :
PH : 93661633
ATTN :

ESTIMATE BILL

Number : EB00005487
Date : 16/06/2020
Case No : AD00011150
Vehicle No : SJJ7842U
Chassis : JTDER12W603000795
Year of Mfr : 2008
Policy No :
Model : TOYOTA WISH 1.8 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE <i>3000</i>	1.0	1,272.00	25	954.00
2	TAILGATE DAMPER RH <i>11</i>	1.0	227.00	X 25	170.25
3	TAILGATE DAMPER LH <i>11</i>	1.0	227.00	X 25	170.25
4	TAILGATE EMBLEM <i>new</i>	1.0	63.00	25	47.25
5	TAILGATE LOGO <i>new</i>	1.0	59.00	25	44.25
6	END PANEL <i>1500</i>	1.0	519.00	25	389.25
7	END PANEL TOP GARNISH <i>new</i>	1.0	245.12	25	183.84
8	REAR BUMPER <i>new</i>	1.0	513.00	25	384.75
9	REAR BUMPER RETAINER RH <i>11</i>	1.0	87.00	X 25	65.25
10	REAR BUMPER RETAINER LH <i>11</i>	1.0	87.00	X 25	65.25
11	REAR BUMPER REFLECTOR LH <i>11</i>	1.0	69.00	X 25	51.75
12	REAR BUMPER CLIP <i>new</i>	4.0	5.00	25	15.00
13	REAR FENDER LAMP LH <i>new</i>	1.0	524.00	25	393.00
List Price - Parts Sub Total					2,934.09
14	REVERSE SENSOR <i>299.10</i>	1.0	280.00	0	280.00
15	REAR BUMPER SPOILER <i>new</i>	1.0	680.00	0	680.00
16	REAR FENDER LH - REPAIR <i>R</i>	1.0			
Special Nett Price - Parts Sub Total					960.00
Parts Total					3,894.09
17	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
18	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
19	ANTI-RUST COATING	1.0	150.00	0	150.00
20	WIRING	1.0	40.00	0	40.00
21	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,140.00
SINGAPORE DOLLARS : SIX THOUSAND FOUR HUNDRED FIFTY-SIX AND CENTS FORTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		6,034.09
			GST 7.00%		422.39
			TOTAL		6,456.48

LKZ Auto Consultants 13/06/2020 09:45 AM

Date of accident: 13/06/2020 09:45 AM. Place : BEDOK SOUTH AVE 3 X BEDOK SOUTH RD JUNCTION

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CUSTOMER SIGNATURE

Acknowledged by Repairer

Signature:

Date: * N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

Page 1 of 1

Issued by : Anyisia