

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 19 June 2020
To : LKK

By Fax: 6256-4315

Attn : Bryan Ang
Tel: 97237799

VEHICLE NO : FBF 1504B
ACCIDENT DATE: 15 June 2020

Yamaha FZ16

Description	Qty	Quotation \$
1 Handle Bar <i>bst</i>	1	160.00 ✓
2 Mirror <i>cut</i>	1 set	190.00 ✓
3 Balancer <i>bst</i>	1 set	180.00 ✓
4 Brake Lever <i>req</i>	1	85.00 X
5 Front Mudguard <i>crack</i>	1	250.00 ✓
6 Fork Tube <i>bst</i>	1 set	480.00 ✓
7 Fork Under Bracket <i>Dem</i>	1	235.00 ✓
8 Front LH Shroud <i>cut</i>	1	190.00 ✓
9 Gear Pedal <i>bst</i>	1	95.00 ✓
10 Front LH Footrest <i>bst / broken</i>	1	85.00 ✓
11 LH Footrest Bracket <i>cut</i>	1	150.00 X
12 Exhaust Guard - Front <i>cut</i>	1	185.00 ✓
13 Exhaust Guard Cover - Rear <i>cut</i>	1	150.00 ✓
14 Gear Shifter <i>bst</i>	1	85.00 ✓
15 Head Lamp Guard LH <i>cut / crack</i>	1	190.00 ✓
16 Rear LH Side Panel <i>req</i>	1	185.00 X
17 Front Rim <i>cut</i>	1	350.00 X

for wheel shaft - 475.00
bst

Sub-Total 3,245.00
Less 10% 324.50
Sub-Total 2,920.50

Acknowledged by Receiver
Signature:
Date:

LKK Auto Consultants hence notify
the Receiver of the following:

- To reserve damaged parts (being reserved)
- To reserve damaged parts (being reserved)
- Parts prices are subject to confirmation
- Third party survey *W/O* "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental items must be reserved and
is subject to final approval from Insurance Company

VEHICLE NO : FBF 1504B

Yamaha FZ16

Nett Items

1	1 set side box - round <i>broken</i>	250.00	150/-
2	Towing fee <i>NH</i>	40.00	<i>NH</i>
3	Remove & replace parts, align & etc	220.00	150/-
4	Remove & replace fork tube, bracket & top up fork oil	150.00	80/-
5	Putty & touch up paint work	250.00	150/-
6	Repress front rim	80.00	20/-
7	Supply body stickers	150.00	60/-
Sub-Total		1,140.00	
Nett Total		4,060.50	

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

S9 MOTOR TRADING PTE LTD

:LG

18/06/2025 @ 1745hrs

NLT *Arthur*

2/sum

4 days.

ngan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: