



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Buss.Reg.No.: 52888887X

QUOTATION

No : QT-000218

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466 FAX : 65073849

Your Ref. : SHC3710D
Vehicle No. : SJM9712H
Make & Model : TOYOTA AXIO
Chasis No. : NZE1416094469
Engine No. : 1NZD169854
Accident Date : 15-06-2020
Policy No. : 2070007717
Date : 17-06-2020
Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	DOOR (L/H/F) ? Dented	1.0	PCS 1,234.72	✓ 1,234.72
2	DOOR (L/H/R) ?	1.0	PCS 1,123.95	✓ 1,123.95
3	DOOR STICKER (FRAME) (L/H/F) ?	2.0	PCS 51.72	✓ 103.44
4	DOOR STICKER (FRAME) (L/H/R) ?	2.0	PCS 51.72	✓ 103.44
5	WINDOW REGULATOR (L/H/F) Dented	1.0	PCS 193.40	✓ 193.40
6	WINDOW REGULATOR (L/H/R) New	1.0	PCS 193.40	X 193.40
7	WINDOW REGULATOR MOTOR (L/H/F) ?	1.0	PCS 562.86	+ 562.86
8	WINDOW REGULATOR MOTOR (L/H/R) ?	1.0	PCS 562.86	+ 562.86
9	DOOR ANTI SPLASH PLASTIC SEAL New	2.0	PCS 96.55	80/SN 193.10
10	DOOR HINGE (R/H LOWER) Best	2.0	PCS 75.18	75.18 150.36
11	DOOR HINGE (R/H UPPER) New	2.0	PCS 75.18	+ 150.36
12	DOOR CHECKER (L/H/R) New	1.0	PCS 132.17	X 132.17
13	DOOR INNER LOCK (L/H/F) Dented	1.0	PCS 441.84	✓ 441.84
14	DOOR WEATHER STRIP (R/H/F) ?	1.0	PCS 171.20	+ 171.20
15	DOOR WEATHER STRIP (R/H/R) ?	1.0	PCS 171.20	+ 171.20
16	DOOR CHANNEL (L/H/F) Best not given	1.0	PCS 135.84	X 135.84
17	BRACKET DOOR CHANNEL (L/H/F) Best	1.0	PCS 85.40	✓ 85.40
18	DOOR STOPPER RUBBER (L/H/F) ?	1.0	PCS 13.97	+ 13.97
19	DOOR STOPPER RUBBER (L/H/R) ?	1.0	PCS 13.97	+ 13.97
20	DOOR INNER TRIM BOARD (L/H/F) Cashed	1.0	PCS 875.24	480.10 875.24
21	DOOR INNER TRIM BOARD CLIP (L/H/F) New	10.0	PCS 4.50	30 45.00
22	DOOR INNER TRIM BOARD CLIP (R/H/R) New	10.0	PCS 4.50	+ 45.00
23	DOOR FRAME BEADING (L/H/F) ?	1.0	PCS 342.84	+ 342.84
24	DOOR FRAME BEADING (L/H/R) ?	1.0	PCS 342.84	+ 342.84
25	DOOR HANDLE (OUTER) (L/H/F) ?	1.0	PCS 328.00	+ 328.00
26	DOOR HANDLE (OUTER) BASE (L/H/F) ?	1.0	PCS 286.76	+ 286.76



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Buss.Reg.No.: 52888887X

QUOTATION

No : QT-000218

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466 FAX : 65073849

Your Ref. : SHC3710D
Vehicle No. : SJM9712H
Make & Model : TOYOTA AXIO
Chasis No. : NZE1416094469
Engine No. : 1NZD169854
Accident Date : 15-06-2020
Policy No. : 2070007717
Date : 17-06-2020
Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
27	WINDOW OUTER RUBBER (L/H/F) <i>see u</i>	1.0 PCS	145.25	<i>+</i> 145.25
28	DOOR CATCH (L/H/F)	1.0 PCS	23.50	<i>+</i> 23.50
29	SWITCH (DOOR) (L/H/F) <i>see u</i>	1.0 PCS	56.40	<i>+</i> 56.40
30	ROCKER PANEL (L/H)	1.0 PCS	414.15	<i>+</i> 414.15
31	CENTER PILLAR (L/H)	1.0 PCS	483.10	<i>+</i> 483.10
32	Discount 25 %			-2,281.39
33	SubTotal (L)			6,844.17
34	SIDE SKIRT (L/H) <i>del</i>	1.0 PCS	500.00	<i>✓</i> 500.00
35	SubTotal (S)			500.00
36	TO PROVIDE UNDER TURFCOAT	1.0 X	60	150.00
37	PANEL BEATING & REPLACING OF THE ABOVE	1.0 X	0.00	100 1,000.00
38	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	0.00	100 1,000.00
39	TO REMOVE, TRANSFER & INSTALL RELATED COMPONENT	1.0 X		<i>+</i> 250.00
40	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X		<i>160 180.00</i>
41	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X		<i>30 80.00</i>
42	SubTotal (LABOUR)			2,660.00

SINGAPORE DOLLAR TEN THOUSAND FOUR AND CENTS SEVENTEEN ONLY

E. & O.E

Total	S\$	10,004.17
Discount	S\$	0.00
Net Total	S\$	10,004.17

Terms: C.O.D.

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

Customer's Signature/Co Stamp

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice, otherwise it is subject to final approval from the company and that this bill is accepted as correct.

Acknowledged by Repairer

Signature:

Date:

ZERO GRAVITY

Admin L
05 Days
H/S 16/06/20