

Fax : 64556384

LOH HENG

Automotive Repair Services
Accident Insurance Claims

18/06/2020

MS First Capital Insurance Ltd

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation (Supplymentary)

Vehicle No. SJX 2948H Audi A4

S/N		Amount (S\$)
A	PART REPLACEMENT	
	Rear right tail lamp panel	\$ 241.00 ✓
	Engine ECU module controller 2035.20 Dd/short	\$ 3,892.00 ✓
	less 5%	\$ 3,926.40
	Cut,reweld tail panel.knock out inner chasis panel. nn	\$ 180.00 X
	Reprogramme and reconfigerate system ECU	\$ 250.00 150/
	GRAND TOTAL OF A & B	\$ 4,356.40