

# Dynamic Autowork Pte.Ltd.

( ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 22.06.20

TO : **AIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SMH5883P**  
MODEL : **JAGUAR XE**  
DATE OF ACCIDENT : 18.06.20  
TIME OF ACCIDENT : 18:00HRS

SAJA B4A X6JC P21619

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                          | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|------------------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT BUMPER <i>reformed</i>                         | 1   | \$ 1,684.10     | \$ 1,684.10      |
| 2   | FRONT BUMPER SENSOR <i>new</i>                       | 4   | \$ 193.35       | \$ 773.40        |
| 3   | FRONT BUMPER SENSOR HOLDER <i>new</i>                | 4   | \$ 17.35        | \$ 69.40         |
| 4   | FRONT BUMPER LOWER GRILLE SIDE GARNISH RH <i>new</i> | 1   | \$ 229.15       | \$ 229.15        |
| 5   | FRONT BUMPER SIDE RETAINER <i>RH new</i>             | 2   | \$ 30.60        | \$ 61.20         |
| 6   | FRONT BUMPER SIDE AIR DUCT <i>cracked</i>            | 1   | \$ 102.80       | \$ 102.80        |
| 7   | FRONT BUMPER BOTTOM COVER GARNISH <i>to 1/2</i>      | 1   | \$ 284.80       | \$ 284.80        |
| 8   | FRONT BUMPER SPONGE <i>new</i>                       | 1   | \$ 386.90       | \$ 386.90        |
| 9   | FRONT FENDER RH <i>RHS</i>                           | 1   | \$ 799.30       | \$ 799.30        |
| 10  | FRONT FENDER COWLING RH <i>new</i>                   | 1   | \$ 303.65       | \$ 303.65        |
| 11  | HEADLAMP RH (LED) <i>lit</i>                         | 1   | \$ 3,960.40     | \$ 3,960.40      |
| 12  | FRONT WATER COOLER RH <i>Dented</i>                  | 1   | \$ 535.50       | \$ 535.50        |
| 13  | FRONT WATER COOLER COWLING <i>to 1/2</i>             | 1   | \$ 268.80       | \$ 268.80        |
| 14  | FRONT WATER COOLER PIPE <i>new</i>                   | 1   | \$ 259.05       | \$ 259.05        |
| 15  | FRONT WHEEL SPORT RIM RH <i>lit</i>                  | 1   | \$ 1,698.70     | \$ 1,698.70      |
| 16  | FRONT ABS SENSOR <i>new</i>                          | 1   | \$ 379.20       | \$ 379.20        |
| 17  | FRONT STEERING RACK AND PINION                       | 1   | \$ 3,968.50     | \$ 3,968.50      |
| 18  | FRONT DRIVESHAFT RH                                  | 1   | \$ 1,448.60     | \$ 1,448.60      |
| 19  | FRONT LOWER ARM RH                                   | 1   | \$ 538.25       | \$ 538.25        |
| 20  | FRONT KNUCKLE ARM C/W BEARING RH                     | 1   | \$ 1,084.15     | \$ 1,084.15      |
| 21  | FRONT WHEEL HUP RH                                   | 1   | \$ 512.80       | \$ 512.80        |
| 22  | FRONT SHOCK ABSORBER RH                              | 1   | \$ 565.25       | \$ 565.25        |

6254.15 SN 1010  
5628.73

TOTAL PRICE \$ 19,913.90  
LESS 10% \$ 1,991.39  
SUB TOTAL PRICE \$ 17,922.51

| S/N | DESCRIPTION                                       | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|---------------------------------------------------|-----|-------------|--------------|
| 1   | FRONT BUMPER CLIP (SET) <i>new</i>                | 1   | \$ 120.00   | \$ 120.00    |
| 2   | FRONT BUMPER LOWER GRILLE SIDE GARNISH CLIP (SET) | 1   | \$ 50.00    | \$ 50.00     |

new new

TO : AIG MOTOR CLAIMS DEPTS  
VEHICLE NO : SMH5883P  
MODEL : JAGUAR XE  
DATE OF ACCIDENT : 18.06.20  
TIME OF ACCIDENT : 18:00HRS

|   |                                              |   |           |           |
|---|----------------------------------------------|---|-----------|-----------|
| 3 | FRONT BUMPER CENTER GRILLE CLIP (SET)        | 1 | \$ 80.00  | \$ 80.00  |
| 4 | FRONT BUMPER BOTTOM COVER GARNISH CLIP (SET) | 1 | \$ 80.00  | \$ 80.00  |
| 5 | FRONT FENDER COWLING CLIP (SET)              | 1 | \$ 80.00  | \$ 80.00  |
| 6 | FRONT WHEEL TYRE RH                          | 1 | \$ 850.00 | \$ 850.00 |
| 7 | COOLANT                                      | 1 | \$ 80.00  | \$ 80.00  |
| 8 | BRAKE OIL                                    | 1 | \$ 50.00  | \$ 50.00  |

TOTAL \$ 1,390.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| S/N | JOB DESCRIPTION                                                                                | PRICE       | ADJUSTED COST |
|-----|------------------------------------------------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS                                                     | \$ 1,400.00 | 400           |
| 2   | TO SPRAY PAINT AFFECTED AREA                                                                   | \$ 1,400.00 | 500           |
| 3   | REFOCUS HEADLAMP BEAM                                                                          | \$ 80.00    | X             |
| 4   | REMOVE AND REFIX FRONT WATER COOLER                                                            | \$ 150.00   | 80            |
| 5   | REMOVE AND REFIX FRONT UNDERCARRIAGE                                                           | \$ 850.00   | X             |
| 6   | FOUR WHEEL ALIGNMENT                                                                           | \$ 120.00   | 80            |
| 7   | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 450.00   | 100           |

TOTAL \$ 4,450.00 1160

ESTIMATE REPORT

TOTAL PARTS COST \$ 19,312.51  
TOTAL LABOUR COST : \$ 4,450.00  
TOTAL REPAIR COST : \$ 23,762.51

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR  
ABBY  
HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total: 7868.73  
4/s 6.2K.

Admin L  
4/s 23/06/20  
05 Days