

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
GRE	GREAT AMERICAN INSURANCE COMPANY			CS3/GAI20006466/E	Etf3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL Date TOWER SINGAPORE 039190				29-06-2020		
			Code:	GAI		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	GBD 5668X	Veh. Ir	nspected	FBR 1660U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CLMOMVC000003834	Excess (\$)		0.00	
	Assign From	SHERY WONG	Assig	n Date	19/06/2020	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA AEROX	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SG4640LJ070587	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/80-14	DUNLC)P	5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-14	DUNLC)P	5 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSPORTION.	STAINED DAMAGES AT THE N/S	BODY A	AND FRONT		
5.	5. General Information					
	Accident Date	30/04/2020	Inspec	ct Date / Time	22/06/2020 (12:29 PM)	
	Survey held at	EQUATOR BROTHERHOOD				
		25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/GAI20006466/Etf3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.