



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

27 JUNE 2015
C 1300 - n/v

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Samsidi Bin Kasan ADDRESS : Blk 903 Tampines Ave 4 #07-292 Singapore 520903 TEL :		WIP : 25659 EXCESS : DATE: 30-Mar-20	
VEH NO :	SMS5431C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6TC2WLAK0319746	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX9	DATE REG.:	28-Feb-20	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER <i>Rebond</i>	1	MTK51-50-221DBB	✓	\$ 1,359.50
2	BRACKET CENTER	1	MKD53-50-251	X	\$ 5.40
3	STAY, REAR BUMPER	2	MTK50-50-271C	X	\$ 21.00
4	CROME CENTER, REAR BUMPER <i>Rebond</i>	1	MTK50-50-369C	X	\$ 241.00
5	COVER UNDER, REAR BUMPER	1	MTK49-50-C51	X	\$ 66.60
6	REAR REINFORCEMENT	1	MTK48-50-260B	X	\$ 553.90
7	RETAINER CENTER, SENSOR <i>Neu</i>	2	MTK80-67-UC5	✓	\$ 31.00
8	SENSOR CENTER, ULTRASONIC <i>Neu Neu</i>	2	MGMC8-67-UC1	X	\$ 401.00
9	PAD PROTECTOR, SENSOR <i>Neu</i>	5	MG001-67-061	✓	\$ 39.00
10	FASTENER, REAR BUMPER	16	MB45A-56-146A	✓	\$ 48.00
11	GROMMET, REAR BUMPER	6	MBHN1-50-021A	✓	\$ 16.20
12	RIVET, REAR BUMPER <i>Neu</i>	6	MB33J-51-833	✓	\$ 45.60
13	CLIP, REAR BUMPER	9	MBGV4-56-145	✓	\$ 26.10
14	SEAL RUBBER, REAR BUMPER	2	MTK48-50-2G2	✓	\$ 27.40
15	CLIP, REAR BUMPER	4	MC274-50-133	✓	\$ 14.80
TOTAL PARTS					\$ 2,896.50
TOTAL PARTS COST					\$ 2,896.50
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			<i>660</i> \$ 1,320.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			<i>630</i> \$ 1,260.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.			NETT \$ 330.00

180

4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	X	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ ¹⁰ 100.00
			TOTAL LABOUR	\$ - \$ 3,860.00
			TOTAL PARTS	\$ - \$ 2,896.50
			TOTAL	\$ - \$ 6,756.50
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

Adrian Lj
P/p 23/06/20
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: