

GBJ100SD.

Nissan NV350

JN1MC2E26Z0030776.

TP Budget Direct.
Shirley.

Rear Bumper to/n.

667.20 ✓

Rear Bumper Clips New

30 ✓

Rear Bumper Side Holder x 02 New

24.2 x 2 = 48.40 +

Reverse Sensor New

280 (SN) +

Tail Lamp LH. Amal

224.80 ✓

922

829.80

Panel Bending
Spray Painting.
Wiring~~300~~ 100~~300~~ 200~~50~~ 30

To remove reverse sensor

~~100~~ 50

480

1,903.36

total 1309.80

L/S: 1K

02 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

200