



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20004538/Qvf3e2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 30-06-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6851R	Veh. Inspected	SGJ 8339K
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VC05/023246	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	18/06/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH 1.8A	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100316041	Colour	GREY
Odometer	675777	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FIRENZA	6 mm
L/H Front Tyre	195/65 R15	FIRENZA	6 mm
R/H Rear Tyre	195/65 R15	FIRENZA	6 mm
L/H Rear Tyre	195/65 R15	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/03/2020	Inspection Date	26/03/2020
Survey held at	BLK 5 DEFU LANE 10 #01-580		
Repairer	Y S AUTOMOBILE SERVICE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------