

NTUC-TUC (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.06.2020

Time: 11:10:19

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305406207
REGN NO : SHC2352K
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 07.01.2019
DATE/TIME IN : 20.06.2020 10:55
ACCIDENT DATE : 20.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2292-G	COVER FRONT BUMPER	1	499.90	25.00	374.92	de ✓
0002	04-01-0302-0633-G	COVER FRONT BUMPER HOLE R	1	28.38	25.00	21.28	mis ✓
0003	04-01-0302-0572-G	HOOD SUB-ASSY	1	950.50	25.00	712.87	bt ✓
0004	04-01-0302-0573-G	FENDER SUB-ASSY FRONT RH	1	933.10	25.00	699.82	bt ✓
0005	04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID	1	86.00	25.00	64.50	ne ✓
0006	04-01-0302-4991-G	LAMP ASSY FOG RH	1	920.00	25.00	690.00	any ✓
0007	04-01-0302-2915-G	UNIT ASSY HEADLAMP RH	1	3,455.00	25.00	2,591.25	any ✓
0008	04-01-0302-2298-G	REINFORCEMENT SUB-ASSY FR	1	696.40	25.00	522.30	X any
0009	04-01-0302-2164-G	GRILLE SUB-ASSY RADIATOR	1	438.00	25.00	328.50	X any
0010	04-01-0302-2971-G	SUPPORT FRONT BUMPER SIDE	1	76.90	25.00	57.67	de ✓
0011	04-01-0302-2974-G	SUPPORT RADIATOR UPPER RH	1	76.10	25.00	57.07	Rx
0012	04-01-0302-2975-G	SUPPORT SUB-ASSY RADIATOR	1	234.70	25.00	176.02	X any
0013	04-01-0302-2277-G	SUPPORT SUB-ASSY RADIATOR	1	361.10	25.00	270.82	X any

03.0

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305406207
REGN NO : SHC2352K
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBR
DATE OF REGN : 07.01.2019
DATE/TIME IN : 20.06.2020 10
ACCIDENT DATE : 20.06.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 04-01-0302-2062-G GRILLE RADIATOR LOWER NO.	1	163.40	25.00	122.55	X un
0015 04-01-0302-0988-G EMBLEM ASSY RADIATOR GRIL	1	88.00	25.00	66.00	48 X un
0016 04-01-0302-2234-G COVER ENGINE UNDER COVER	1	180.00	25.00	135.00	X un
0017 04-01-0302-2233-G ENGINE UNDER COVER NO.1	1	457.40	25.00	343.05	X un

5212.31

SUB-TOTAL : 7,233.62

JOB NATURE

0000 PB	PANEL BEATING	1000.00	640.
0001 SP	SPRAYPAINT CHARGE	800.00	600.
0002 17-01	CHECK ALL LIGHTING	50.00	30.
0003 18-01	TO VAC. & TOP UP A/C GAS	120.00	X un.
0004 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30 1300
		5212.31	
		1300	
		SUB-TOTAL : 2,020.00	

Tanflin 97495747
'wp'

5212.31
1300
\$6512.31

P/P Resurvey before paint
22/6/20 @ 3pm
3-4 days

Tanflin @ lkhant.wn.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation or arbitration is allowed
- Supplier's price must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature

Date