

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: MFL2019D0000017/03&04/CM Date: 25<sup>th</sup> Jun 2020

Our Ref: CS1/III20006579/Gyf3e2

## M/s India International Insurance PL

64 Cecil Street #05-02 IOB Building Singapore 049711

Dear Sir / Madam.

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: JQB 737** 

INSURED VEHICLE: GW 5853T ACCIDENT DATE: 14/01/2019

We thank you for your instruction on 23/06/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of JQB 737 from M/s Priority Services.
- b) Final Repair Bill of JQB 737 from M/s Jec Auto Service.
- c) Singapore Accident Statement of Vehicles GW 5853T.
- d) Police Report of Vehicles JQB 737 and GW 5853T.
- e) Colour damaged vehicle photographs of JQB 737.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : JQB 737

Make & Model : Lexus ES250 (A)

Year of Registration : 2014

Chassis Number : JTHBJ1GGX020447747

Engine Capacity : 2494 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.