

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 15 Jul 2020

Preliminary Advice

Insured Vehicle No	: SLU2480G	Accident Date	: 21/06/2020
TP Vehicle No	: SMN5018P	Assignment Date	: 03/07/2020
Make	: HYUNDAI ELANTRA	Est. Duration of Repair	: 9
Date of Inspection	: 24/6/20		
Inspection At	: N-51 AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,922.16
Revised Amount	:S\$	8,900.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,900.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.