

Estimate

23/06/2020

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- **XA025**

Page # :- 1

Veh # :- SCM886G

Veh Model :- TOYOTA ESTIMA AERAS 2.4

Estimate# :- CK420740

Claim # :-

ACC. Date :- 22/06/20

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : **(65) 6272 3892**
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT	1 PC	1,753.80	1,753.80
2.	REAR BOOT LOGO	1 PC	75.20	75.20
3.	REAR BOOT EMBLEM "ESTIMA"	1 PC	79.80	79.80
4.	REAR BOOT EMBLEM "AERAS"	1 PC	79.20	79.20
5.	REAR BOOT CHROME	1 PC	229.80	229.80
6.	REAR BOOT W/S MOULDING	1 SET	211.80	211.80
7.	REAR BOOT LOCK TOP	1 PC	490.39	490.39
8.	REAR BOOT LOCK COVER TOP	1 PC	94.30	94.30
9.	REAR BOOT LOCK LOWER	1 PC	45.90	45.90
10.	REAR BOOT LOCK LOWER COVER	1 PC	42.80	42.80
11.	REAR BOOT RUBBER	1 PC	372.90	372.90
12.	REAR BOOT INNER TRIM	1 PC	317.20	317.20
13.	REAR BOOT HINGE L+R	2 PC	69.30	138.60
14.	REAR BOOT INNER HANDLE	1 PC	63.80	63.80
15.	REAR BOOT PUSH BUTTOM	1 PC	178.60	178.60
16.	REAR BOOT STICKER (WARNING SIGN)	1 PC	110.20	110.20
17.	REAR BOOT INNER GROMMET	10 PC	7.10	71.00
18.	REAR BOOT LAMP LH	1 PC	440.90	440.90
19.	REAR LAMP LH	1 PC	475.80	475.80
20.	REAR END PANEL	1 PC	754.70	754.70
21.	REAR END PANEL TRIM TOP	1 PC	294.80	294.80
22.	REAR END PANEL TRIM LOW	1 PC	199.50	199.50
23.	REAR END PANEL TRIM CLIPS	7 PC	6.50	45.50
24.	REAR SIDE GARNISH L+R	2 PC	552.70	1,105.40
25.	REAR FLOOR PANEL	1 PC	805.90	805.90
26.	REAR FLOOR PANEL CARPET	1 PC	584.70	584.70
27.	REAR BUMPER	1 PC	290.00	290.00
28.	REAR BUMPER SPONGE L+R	2 PC	55.00	110.00
29.	REAR BUMPER TOW COVER LH	1 PC	30.00	30.00
30.	REAR BUMPER REFLECTOR LH	1 PC	55.00	55.00
31.	REAR BUMPER SIDE SHIELD L+R	2 PC	75.00	150.00
LIST TOTAL S\$				9,697.49
25% DISCOUNT S\$				-2,424.37
				7,273.12
SPECIAL NET ITEMS :				
1.	REAR BOOT SEALANT	1 PC	50.00	50.00
2.	REAR BUMPER SENSOR	1 PC	200.00	200.00
SPECIAL NET TOTAL S\$				250.00

LABOUR :

TO CUT & WELD REAR END PANEL, REAR FLOOR
PANEL. TO REPAIR REAR FENDER LH & RH, REAR
CHASSIS MEMBER LH & RH. TO REMOVE & REFIX
DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED
AREAS

1,100.00

Estimate

23/06/2020

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- **XA025**

Page # :- 1 138435

Veh # :- SCM886G

Veh Model :- TOYOTA ESTIMA AERAS 2.4

Estimate# :- CK420740

Claim # :-

ACC. Date :- 22/06/20

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : **(65) 6272 3892**
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	TO SPRAY AFFECTED AREAS			1,000.00
	TO REMOVE & REFIX REAR W/S GLASS			150.00
	TO REMOVE & REFIX REAR BOOT MECHANISM CHECK & TEST WIPER MOTOR, REAR CENTRE LOCKING POWER LOCK SYSTEM			80.00
	TO REMOVE & REFIX THIRD ROLL CUSHION,SDIE COVER, SAFETY BELT AND OTHER ATTACHMENT PARTS			100.00
	TO REMOVE & REFIX REVERSE SENSOR & CHECK WATER SEEPAGE			80.00
	TO RUST PROOF AFFECTED AREA			80.00
	LABOUR TOTAL S\$			2,590.00

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	10,113.12
GST @ 7 %	707.92
AMOUNT DUE S\$	10,821.04

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**