

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI20006599/	Asf3e2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 22-07-2020 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7556S	Veh. Inspected	SMM 2883H
	Policy No.		Coverage (\$)	0.00
	Claim No.	D20002505MFSH	Excess (\$)	0.00
	Assign From	KAREN TAN	Assign Date	23/06/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	RU11319019	Colour	WHITE
	Odometer	12545	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	FALKEN	6 mm
	L/H Front Tyre	215/55 R17	FALKEN	6 mm
	R/H Rear Tyre	215/55 R17	FALKEN	6 mm
	L/H Rear Tyre	215/55 R17	FALKEN	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	20/06/2020	Inspection Date	24/06/2020
	Survey held at	YSK AUTO WORKSHOP		
		1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883		
5a.	a. Remarks			
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			