

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBD4770P

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2090483 /WS

Date: 27 Jun 2020

Policy No: DMCVSN1546101904

Veh Reg No: GBD4770P

Make/Model: NISSAN CABSTAR 3.0
 5M/T ABS 2DR 2WD
 DURO 5

Chassis No: JN1SC2F24Z0856618

Engine No: ZD30342688K

Reg. Date: 29/10/2014

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 22/06/2020

TP Veh Reg No: GZ7483Z

Not Authorized

11 Days @ 3000
 Recovery After Claim

4 days

Estimate Repair Cost to Vehicle No :GBD4770P

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR TAILGATE	1,459.60	1 PC	1,459.60	✓
2 REAR TAILGATE STICKER "NISSAN"	169.00	1 PC	169.00	✓
3 REAR TAILGATE LH HINGE	182.90	1 PC	182.90	✓
4 REAR TAILGATE LH SAFETY LOCK	36.00	1 PC	36.00	✓
5 LH TAILLAMP	203.50	1 PC	203.50	✓
6 RH TAILLAMP	203.50	1 PC	203.50	✓
7 RH TAILLAMP PANEL	120.00	1 PC	120.00	✓
			2,374.50	
	Less 10%		237.45	2,137.05
Special Net				
8 "70KM/H" STICKER	10.00	1 PC	10.00	✓
9 "13PAX" STICKER	10.00	1 PC	10.00	✓
10 ISET REVERSE SENSOR	200.00	1 PC	200.00	✓
11 LH STOPPER	15.00	1 PC	15.00	✓
12 TAILGATE INNER PROTECTOR	280.00	1 PC	280.00	✓
13 TAILGATE INNER PROTECTOR CLIPS	30.00	1 PC	30.00	✓
14 REAR NUMBER PLATE	30.00	1 PC	30.00	25.00
			575.00	575.00
Labour				
15 REMOVE AND REFIT TAILLAMPS, TAILGATE ASSY. TO KNOCK AND REPAIR REAR END PANEL, REAR CHASSIS,FLOORBOARD PANEL, LH CORNER PILLAR, LH SIDE GATE AND LOWER PANEL AND REALIGN THE SAME.	800.00	1 LA	800.00	600
16 PUTTY AND RESPRAY TAILGATE, REAR END PANEL, LH SIDE GATE & LOWER PANEL, REAR LH CORNER PILLAR AND REAR LH CHASSIS.	800.00	1 LA	800.00	600
			1,600.00	1,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ 4,312.05

Add GST @ 7% 301.84

Total Amount Payable S\$ 4,613.89

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE