

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

DATE: 23. Jun. 2020

VEHICLE NO : SHA9517S

MAKE : HYUNDAI

DOA: 23. Jun. 2020

CHINA

MODEL : IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	Rear Bumper			\$459.40	Rx
1	Rear Fender - LH			\$1,768.30	Rx
1	Rear Wheel Cover - LH		277.12	\$346.40	cut
1	Rear Door - LH			\$1,789.90	Rx
1	Front Door - LH			\$1,797.20	Rx
1	Front Fender - LH		392.56	\$490.70	bt
1	Front Wheel Cover - LH		277.12	\$346.40	cut
1	Front Bumper - LH			\$418.30	Rx
	Supp < Moulding assy-side moulding assy-w/c	290 116-20	20% 232 92.96		
<b>SUB TOTAL</b>				<b>\$7,416.60</b>	
<b>LESS 20% DISCOUNTED TOTAL</b>				<b>\$1,483.32</b>	
<b>DISCOUNTED TOTAL</b>				<b>\$5,933.28</b>	
				<b>1271.76</b>	
1	Rear Door APP Sticker			\$80.00	cut ✓ <b>Nett</b>
1	Front Door COMFORTDELGRO Sticker			\$75.00	cut ✓ <b>Nett</b>
				<b>\$155.00</b>	155
<b>Labour Charge</b>					
1	Labour Charge			\$1,200.00	000
1	Spray Painting Charge			\$1,200.00	1000
1	Tuff Kote			\$100.00	40
1	Wiring Charge			\$100.00	nm X
2	Transfer of Doors - Frt, Rear			\$300.00	nm X \$150.00
<b>TOTAL LABOUR</b>				<b>\$2,900.00</b>	1840
<b>ESTIMATE TOTAL</b>				<b>\$8,988.28</b>	
				<b>3266.76</b>	
				<b>4 days</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanphim 97495747 240pm  
wp' 24/6/2020  
p/p Resurvey before paint  
3-4 days  
tanphim@lkkauto.com

\* BSD - Blind Spot Detetion \*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Larry Ng