

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	OD	Ref. No:	YTMG/OD/2006/016
Policy No:	PNMC2018-00005135-01	Date of Loss:	21/06/2020
Vehicle Reg. No.:	FBM4861M	Driveable?	yes
Driver Age:	22/06/1962	Third Party Vehicle No.:	SHA5745B
Any Injuries?	yes	Contact No:	97301060
Insured/Claimant:	ZOLKAPELI BIN ABDUL	Driver:	ZOLKAPELI BIN ABDUL

Make/Model:	Honda, CB190X	Vehicle Reg. Date:	28/08/2018
Vehicle Colour:		Engine Number:	
Chassis No:	LWBPCL1A8H1000726	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - CHANGE/CROSS LANE
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS	Amount
Parts	4,239.00
Miscellaneous Items	325.00
Labour	780.00
Paintwork Labour	450.00
Towing	0.00
Gross Total(S\$):	5,794.00
GST 7.00%(S\$):	405.58
Nett Amount(S\$):	6,199.58

This claim is handled by: Sky Toh T C

PAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT SIDE FAIRING LH ?	474.00	-10.00	426.60
2	1	FRONT SIDE FAIRING RH ?	474.00	-10.00	426.60
3	1	FRONT SIDE INNER FAIRING LH ?	455.00	-10.00	409.50
4	1	FUEL TANK FAIRING LH ?	308.00	-10.00	277.20
5	1	FRONT SIDE INNER FAIRING INNER ? PROTECTOR LH	290.00	-10.00	261.00
6	1	CENTRE TOP FAIRING LH / SCR.	341.00	-10.00	306.90
7	1	CENTRE BOTTOM FAIRING LH / CRA	307.00	-10.00	276.30
8	1	FRONT HANDLE BAR X R	508.00	-10.00	457.20
9	1	FRONT HANDLE BAR HAND GUARD LH / SCR.	165.00	-10.00	148.50
10	1	FRONT HANDLE BAR HAND GUARD RH / CRA	165.00	-10.00	148.50
11	1	FRONT FOOT LEVER LH / BR	145.00	-10.00	130.50
12	1	REAR FOOT REST LH / SCR	45.00	-10.00	40.50
13	1	REAR FOOT REST BRACKET LH / SCR.	165.00	-10.00	148.50
14	1	SIDE STAND	120.00	-10.00	108.00
15	1	FRONT FORK LH X SVC	374.00	-10.00	336.60
16	1	FRONT FORK RH X SVC	374.00	-10.00	336.60

Total Parts (\$\$) 4,239.00

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BOX / SCR,	260.00	0.00	260.00
2	1	REAR BOX TRAY X R	65.00	0.00	65.00

Sub Total (\$\$) 325.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	20.00	0.00	20.00 ✓
2	1	To Dismantle and Refit Front Undercarriage.	220.00	0.00	220.00 X
3	1	To Conduct Wheel Balancing	60.00	0.00	60.00 ✓
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	480.00	0.00	480.00 200

Gross Labour Cost (\$\$) 780.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	70.00	0.00	70.00 30
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and	380.00	0.00	380.00 200?

Repair dy - 3days
Sun Pm (Lkk)
24/06/2020
TP without prejudice.
L/S
After paint photo.

Notes On Paint Work Labour
Qty Particulars

Amount

%Disc

After
Disc

Waxing are also available.

Gross Labour Cost (S\$)

450.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: