



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20006646/Dsf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 20-07-2020



Code : UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 6496H	Veh. Inspected	GZ 7483Z
Policy No.		Coverage (\$)	0.00
Claim No.	M12D13432007	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	24/06/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JTFUF34Y303012120	Colour	SILVER
Odometer	487595	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14C	MICHELIN	5 mm
L/H Front Tyre	185 R14C	MICHELIN	5 mm
R/H Rear Tyre	155 R12C (D)	FALKEN	5/5 mm
L/H Rear Tyre	155 R12C (D)	FALKEN	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/06/2020	Inspection Date	25/06/2020
Survey held at	GOH LEE HWA AUTOMOBILE PTE LTD BLK.5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**