

# SIN FATT DIESEL MOTOR

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

HP: 92712214

Business Reg . No : 377435/00K

25<sup>th</sup> JUNE 2020

WTC M&E PTE LTD  
BLOCK 3020A UBI ROAD 1  
# 01-33  
Singapore 408714

Accident date: 24<sup>th</sup> JUNE 2020

Estimated repair cost for vehicle no: GBG3994B NISSAN NV200 1.6 (A) '17

S/n	Qty	Items	U/price	Amount
				\$958.20
1	1	Front Bonnet		\$85.20
2	1	Front Bonnet Lock		\$112.20
3	1	Front Bonnet Lock Panel		\$824.40
4	2	Front Head Lamp	\$412.20	\$135.20
5	2	Front Head Lamp Lower Bracket	\$67.60	\$697.20
6	2	Front Head Lamp Lower Cover	\$348.60	\$90.40
7	2	Front Head Lamp Lower Cover Side Bracket	\$45.20	\$44.00
8	8	Front Head Lamp Lower Cover Clips	\$5.50	\$612.20
9	1	Front Bumper		\$20.80
10	8	Front bumper clips	\$2.60	\$96.40
11	2	Front Bumper Side Bracket	\$48.20	\$50.00
12	1	Front Bumper Number Plate		\$65.00
13	10	Front Bumper Clips	\$6.50	\$280.70
14	1	Front Bumper Inner Sponge		\$591.90
15	1	Front Bumper Reinforcement		\$295.70
16	1	Front Support Panel Top		\$253.50
17	1	Front Support Panel Lower		\$92.60
18	2	Front Support Panel Side Cover	\$46.30	\$65.00
19	10	Front Support Panel Side Cover Clips	\$6.50	\$299.20
20	1	Front Grille		\$55.20
21	1	Front Grille Emblem Logo		\$44.00
22	8	Front Grille Clips	\$5.50	\$220.00
23	1	water pump		\$596.30
24	1	Front Radiator		\$661.20
25	1	Front Air-Con Condenser		\$2,250.00
26	1	Rear Boot Lid		\$152.20
27	1	Rear Boot Lid Inner Lock		\$77.40
28	1	Rear Boot Lid L/H NV200 Logo		\$215.20
29	1	Rear Boot Lid Center Moulding		\$55.00
30	10	Rear Boot Lid L/H Inner Trim Board Clips	\$0.00	\$143.60
31	1	Rear Boot Lid Inner Rubber		\$35.20
32	1	Rear Boot Lid R/H Logo		\$300.00
33	1	Rear Bumper Reverse Sensor-set		\$30.00
34	1	Rear Boot Lid L/H 70KM/H Logo		\$262.40
35	2	Rear Boot Lid Lower Hinge	\$131.20	\$112.00
36	1	Rear Boot Lid Windscreen Seal		\$512.20
37	1	Rear Bumper	\$35.20	\$70.40
38	2	Rear Bumper Side Bracket	\$6.50	\$65.00
39	10	Rear Bumper Clips		\$125.20
40	1	Rear Bumper Inner Sponge		\$285.20
41	1	Rear End Panel Outer		\$841.80
42	1	Rear End Panel Inner		\$55.50
43	1	Rear End Panel Top Garnish		\$1,353.40
44	1	Rear Floor Panel		

45	2	Rear Tail Lamp	\$315.20	\$630.40
46	1	Rear Spare Tyre Bracket		\$212.70
47	1	Rear Exhaust		\$825.00

**Subtotal :-** \$15,856.30

<b>Labour charges</b>	<b>\$100.00</b>
-----------------------	-----------------

### To remove & refit reverse sensor

To remove & refit rear windscreen

Gum

To remove & refix rear exhaust

to Remove & Refix front windscreen

Gum

To remove & re-fix front air-con condenser,  
Radiator & top up gas

### To Check Wiring

**Tuff kote** **Röer**

Panel beating

### Spray painting

Subtotal :-	\$4,310.00
-------------	------------

**Total:-** \$20,166.30



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	695E

**Vehicle Details**

Vehicle No.:	GBG3994B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Jun 2020
Vehicle Make:	NISSAN
Vehicle Model:	NV200 DX 1.6 A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	HR16081471D
Chassis No.:	VM20102978
Maximum Power Output:	-
Open Market Value:	\$18,909.00
Original Registration Date:	02 Aug 2017
First Registration Date:	02 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$946.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	01 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$28,559.00
<b>Total Rebate Amount:</b>	<b>\$28,559.00</b>

The information contained herein is correct as at 25 Jun 2020

OK