

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM20006663/Aps3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Date: 07-08-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 303X	Veh. Inspected	SMH 8860K
	Policy No.	VFX/P2271004	Coverage (\$)	0.00
	Claim No.	S0M02PTG	Excess (\$)	0.00
	Assign From		Assign Date	25/06/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP51330682	Colour	SILVER
	Odometer	94841	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/55 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/55 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/55 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	22/06/2020	Inspection Date	30/06/2020
	Survey held at	SM AUTOMOTIVE		
	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			