

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

# ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Online Service Booking  
[www.toyota.com.sg](http://www.toyota.com.sg)  
Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

|                                                                                                                        |  |                                        |  |                                                                                     |  |
|------------------------------------------------------------------------------------------------------------------------|--|----------------------------------------|--|-------------------------------------------------------------------------------------|--|
| Account Detail                                                                                                         |  | Account No<br><b>S1000005 / ICFIC1</b> |  | Customer Detail                                                                     |  |
| MS First Capital Insurance Ltd<br>36 Robinson Road<br>#16-01 City House<br>Singapore 068877<br>Attn: Motor Claims Dept |  | Document No<br><b>0</b>                |  | Mdm Beatrice Wong Man Ling<br>310 Tampines Street 32<br>#12-130<br>Singapore 520310 |  |
|                                                                                                                        |  | Document Date<br><b>25/06/2020</b>     |  | Mobile: 90032272                                                                    |  |

| Year | Make  | Model | Reg Date   | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|------|-------|-------|------------|------------|------------|--------|------------------|
| 17   | ANTGT | L1    | 24/11/2017 | SLU2628Z   | 0          | 20118  | 67/DS/SLU2628Z   |

| Chassis No        | Engine No  | Terms | Service Engineer | Vehicle In       | Collected On    |
|-------------------|------------|-------|------------------|------------------|-----------------|
| JTEKB3GH30J000872 | 8ARZ099226 | 60    | Sam San Joi      | 24/06/2020 10.45 | --/--/---- 0.00 |

| L  | Cd | Job/Parts Description                                                                                                                                                 | Qty   | Unit Price | Disc % | Amount       |
|----|----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------------|--------|--------------|
| 1  | Z  | BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT<br>TP-SH8448Y ACC DATE:23/06/2020<br>DRIVE IN:24/06/2020<br>DATE-IN: DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORISED ON: |       |            |        | ✓ 30.00      |
| 2  | B  | BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR                                                                                                                      |       |            |        | ✓ 180.00     |
| 3  | B  | BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST                                                                                                                      |       |            |        | ✓ 180.00     |
| 4  | B  | BP-LAB2 REMOVE & INSTALL REAR COMPARTMETN CARPET<br>, GARNISH AND TRIMMING TO ASSIST REPAIR                                                                           |       |            |        | ✗ 360.00     |
| 5  | B  | BP-ECU2 TO RESET ECU AND REPROGRAMME                                                                                                                                  |       |            |        | ✓ 180.00     |
| 6  | B  | BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS<br>STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS                                                                        |       |            |        | 720 2880.00  |
| 7  | B  | BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR<br>EAS                                                                                                               |       |            |        | 1180 2360.00 |
| 8  | 1  | T52159-48933 COVER, RR BUMPER <i>behind</i>                                                                                                                           | 1.00  | 904.00     |        | ✓ 904.00     |
| 9  | 2  | T52156-48050 SUPPORT, RR BUMPER <i>front</i>                                                                                                                          | 1.00  | 82.70      |        | ✗ 82.70      |
| 10 | 3  | T52155-48050 SUPPORT, RR BUMPER                                                                                                                                       | 1.00  | 82.70      |        | ✗ 82.70      |
| 11 | 4  | T52169-48100 COVER, RR BUMPER, <i>cut</i>                                                                                                                             | 1.00  | 466.00     |        | ✓ 466.00     |
| 12 | 5  | S52161-0K040 CLIPS <i>new</i>                                                                                                                                         | 10.00 | 4.10       |        | ✓ 41.00      |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

|                                            |                                       |                   |            |
|--------------------------------------------|---------------------------------------|-------------------|------------|
| For & on behalf of<br><b>Borneo Motors</b> | Customer's Signature                  | Change Summary    | Total      |
|                                            | Please acknowledge receipt of vehicle | Parts             | Less       |
|                                            |                                       | Labour            |            |
|                                            |                                       | Materials         |            |
|                                            |                                       | Lubrication/Fluid | Amount Due |
|                                            |                                       | Others            |            |

PLEASE TEAR ALONG PERFORATED LINE

4221009

TO SECURITY GUARD

4221009

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/06/2020  
TIME 16:12

VEHICLE NO SLU2628Z

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

Inchcape



Borneo Motors (Singapore) Pte Ltd

Online Service Booking

www.borneomotors.com.sg

Toyota Body Care Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!

|                                                                                                                        |  |                                        |  |                                                                                     |  |
|------------------------------------------------------------------------------------------------------------------------|--|----------------------------------------|--|-------------------------------------------------------------------------------------|--|
| Account Detail                                                                                                         |  | Account No<br><b>S1000005 / ICFIC1</b> |  | Customer Detail                                                                     |  |
| MS First Capital Insurance Ltd<br>36 Robinson Road<br>#16-01 City House<br>Singapore 068877<br>Attn: Motor Claims Dept |  | Document No<br><b>0</b>                |  | Mdm Beatrice Wong Man Ling<br>310 Tampines Street 32<br>#12-130<br>Singapore 520310 |  |
|                                                                                                                        |  | Document Date<br><b>25/06/2020</b>     |  | Mobile: 90032272                                                                    |  |

  

| Year | Make  | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks     |
|------|-------|-------|----------|------------|------------|--------|----------------------|
| 17   | ANTGT | L1    | ASU60R   | 24/11/2017 | SLU2628Z   | 0      | 20118 67/DS/SLU2628Z |

  

| Chassis No        | Engine No  | Terms | Service Engineer | Vehicle In       | Collected On    |
|-------------------|------------|-------|------------------|------------------|-----------------|
| JTEKB3GH30J000872 | 8ARZ099226 | 60    | Sam San Joi      | 24/06/2020 10.45 | --/--/---- 0.00 |

  

| L  | Cd | Job/Parts Description                        | Qty  | Unit Price | Disc % | Amount    |
|----|----|----------------------------------------------|------|------------|--------|-----------|
| 13 | 6  | T52615-48230 ABSORBER, RR BUMPER ?           | 1.00 | 122.60     |        | ✓ 122.60  |
| 14 | 7  | T58307-48120 PANEL SUB-ASSY, BODY P/R        | 1.00 | 1006.40    |        | ✓ 1006.40 |
| 15 | 8  | T48691-48030 DAMPER, SUSPENSION new          | 1.00 | 1343.10    |        | ✓ 1343.10 |
| 16 | 9  | T67005-48350 PANEL SUB-ASSY, BACK P/R        | 1.00 | 2378.00    |        | ✓ 2378.00 |
| 17 | 0  | T75442-48140 PLATE, BACK DOOR new            | 1.00 | 73.70      |        | ✓ 73.70   |
| 18 | 1  | SPZQ31-13020 Badge Assy, Engine Mark RHS new | 1.00 | 17.52      |        | ✓ 17.52   |
| 19 | 2  | T89341-58060 D1 SENSOR, ULTRASONIC, ?        | 2.00 | 481.90     |        | ✓ 963.80  |
| 20 | 3  | T89348-58070 D0 RETAINER, ULTRASONIC ?       | 2.00 | 21.30      |        | ✓ 42.60   |
| 21 | 4  | T89348-58120 RETAINER, ULTRASONIC ?          | 2.00 | 16.00      |        | ✓ 32.00   |

  

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

  

|                                                                                     |                                       |                   |          |                                                              |
|-------------------------------------------------------------------------------------|---------------------------------------|-------------------|----------|--------------------------------------------------------------|
| For & on behalf of<br><b>Borneo Motors</b>                                          | Customer's Signature                  | Change Summary    | Total    | 13,726.12                                                    |
|  | Please acknowledge receipt of vehicle | Parts             | 7,556.12 | GST 7.00% 960.83<br>Less 0.00<br><b>Amount Due 14,686.95</b> |
|                                                                                     |                                       | Labour            | 6,170.00 |                                                              |
|                                                                                     |                                       | Materials         | 0.00     |                                                              |
|                                                                                     |                                       | Lubrication/Fluid | 0.00     |                                                              |
|                                                                                     |                                       | Others            | 0.00     |                                                              |

Adrian Lij  
P/P 30/06/20  
04 Days.

PLEASE TEAR ALONG PERFORATED LINE

4221010

4221010

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 25/06/2020  
TIME 16:12

VEHICLE NO SLU2628Z

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

**Borneo Motors**