

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 24-Jun-20

INSURANCE: First Capital

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHC2905R

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>Cut</i>	1	\$458.60	\$458.60
REAR BUMPER RE-INFORCEMENT <i>NH</i>	1	\$318.80	\$318.80
REAR BUMPER LOWER COVER <i>NH</i>	1	\$552.60	\$552.60
REAR BUMPER SIDE RETAINER <i>side mainly broken</i>	1	\$112.70	\$112.70
REAR BUMPER TOWING COVER <i>NH</i>	1	\$82.70	\$82.70
REAR BUMPER CLIPS <i>NH</i>	1	\$22.00	\$22.00
REAR BUMPER UPPER STOPPER (RH) <i>NH</i>	1	\$76.40	\$76.40
ARM SUB-ASSY, REAR BUMPER, RH <i>NH</i>	1	\$139.60	\$139.60
REAR BUMPER UNDER SIDE COVER (RH) <i>deformed</i>	1	\$232.00	\$232.00
SEAL, REAR BUMPER SIDE, RH <i>cut</i>	1	\$148.40	\$148.40
TAIL LAMP ASSY (UPPER) <i>crack N/S</i>	1	\$557.90	\$557.90
TAIL LAMP ASSY (LOWER) <i>crack N/S</i>	1	\$548.40	\$548.40
TAIL LAMP QUARTER PANEL <i>NH</i>	1	\$216.00	\$216.00
TAIL LAMP SIDE COVER <i>NH</i>	1	\$256.00	\$256.00
REAR TAILLAMP GUIDE - WHITE <i>NH</i>	2	\$95.30	\$190.60
REAR END PANEL <i>NH</i>	1	\$602.10	\$602.10
REAR END PANEL GARNISH <i>NH</i>	1	\$161.80	\$161.80
REAR WIRING ASSY <i>NH</i>	1	\$582.40	\$582.40
REAR FIBER TOOL BOX TRIM (RH) <i>NH</i>	1	\$598.00	\$598.00
SPARE TYRE SIDE PANEL (RH) <i>NH</i>	1	\$196.50	\$196.50
REAR EXHAUST PIPE <i>NH</i>	1	\$1,163.40	\$1,163.40
REAR EXHAUST PIPE HANGER <i>NH</i>	1	\$40.70	\$40.70
REAR EXHAUST PIPE INSULATOR <i>NH</i>	1	\$314.60	\$314.60
REAR FENDER, RH <i>Distorted</i>	1	\$836.70	\$836.70
REAR FENDER INNER PANEL (RH) <i>NH</i>	1	\$728.00	\$728.00
REAR FENDER OUTER PANEL, RH <i>NH</i>	1	\$486.00	\$486.00
REAR FENDER SHIELD (RH) <i>tear / deformed</i>	1	\$174.20	\$174.20
REAR FENDER TRIMBOARD (RH) <i>NH</i>	1	\$725.00	\$725.00
REAR FENDER AIR DUCT <i>svc</i>	1	\$165.10	\$165.10
Rocker Panel Outer Garnish <i>NH</i>	1	\$576.00	\$576.00
Rocker Panel Outer <i>NH</i>	1	\$519.80	\$519.80
REAR TYRE RIM (RH) <i>cut / distorted</i>	1	\$1,555.00	\$1,555.00
REAR WHEEL HUB CAP (RH) <i>NH</i>	1	\$177.70	\$177.70
REAR WHEEL BEARING & HUB assy <i>2 Distorted</i>	1	\$610.20	\$610.20
REAR CROSS MEMBER <i>2 distorted / Bt</i>	1	\$2,200.40	\$2,200.40
REAR SHOCK ABSORBER <i>2 distorted</i>	1	\$118.30	\$118.30
REAR SHOCK ABSORBER MOUNTING <i>NH</i>	1	\$125.30	\$125.30
REAR LOWER ARM <i>2 distorted</i>	1	\$497.50	\$497.50
REAR UPPER ARM <i>2 distorted</i>	1	\$356.80	\$356.80
REAR KNUCKLE ARM <i>2 distorted</i>	1	\$810.60	\$810.60
REAR COIL SPRING <i>NH</i>	1	\$191.40	\$191.40

REAR COIL SPRING MOUNTING NW	1	\$125.70	\$125.70	X
REAR BRAKE ABS SENSOR (WIRE) NW	1	\$278.80	\$278.80	X
REAR STABILIZER BAR NW	1	\$311.50	\$311.50	X
REAR STABILIZER LINK NW	1	\$151.60	\$151.60	X
REAR TRAILING ARM 2 distance	1	\$314.20	\$314.20	2✓
REAR ASSIST ARM 2 distance	1	\$342.20	\$342.20	2✓
			\$19,950.20	
SUB TOTAL			\$3,990.04	
LESS 20% 25%			\$15,960.16	
DISCOUNTED TOTAL				
REAR TYRE (RH) S/V	SN 1	\$216.00	\$216.00	X
			\$216.00	
SUB TOTAL				
Labour Charge	1	\$1,600.00	\$1,600.00	800/-
Panel Beating	1	\$1,200.00	\$1,200.00	600/-
Spray Painting Charge	1	\$140.00	\$140.00	30/-
Wiring Charge	1	\$140.00	\$140.00	40/-
Tuff Kote	1	\$80.00	\$80.00	NW
Towing Charge	1	\$150.00	\$150.00	80/-
Remove/Refix Cushion & Upholstery Rear	1	\$120.00	\$120.00	40/-
Remove/Refix Reverse Sensor	1	\$400.00	\$400.00	120/-
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	NW
Re-set Rear ABS System	1	\$80.00	\$80.00	NW
Remove/Refix Fuel Tank	1	\$80.00	\$80.00	NW
Remove/Refix Exhaust Pipe	1	\$120.00	\$120.00	60/-
Four Wheel Alignment	1	\$550.00	\$550.00	180/-
Diagnostic & Resetting To Erase Fault Code				
			\$5,060.00	
TOTAL LABOUR				
			\$21,236.16	
ESTIMATE TOTAL				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

25/06/2020 @ 1730hrs
 Not Antenna
 4pm 7 days.

(Signature)
 JKK And
(Signature)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: