

Occupation:

INDIA INTERNATIONAL INSURANCE PTE LTD

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III-Direct Settlement (I	PODS)	
India Ref: MCT20060235 Claimant Ref: FBM9732U		
We/I, <u>Ban Hock Hin Co. Pte Ltd</u> ("the workshop") he with the appointed Surveyor of India International Insurance Pte Ltd <u>LKI</u> of Surveyor) with respect to the amount claimed for S\$ 1,859.23 use/rental), S\$ 7.45 (search fee), vehicle no. FBM9732U that was on <u>22/06/2020</u> (date) at <u>PASIR PANJANG RD FILTER TO ALEXANDRA</u> vehicle). This is pursuant to the inspection conducted on <u>26/06/2020</u> (date)	KAUTO CONS (repair cos damaged pursuan RD (location) involvi	ULTANTS PTE LTD_ (name t), S\$60.00 (loss of t to the accident which occurred SHB6232C (insured
We/I confirm that we/I are/am authorized by the owner BAN HOC claimant") of vehicle no.FBM9732U to make the claim as set out in the a the matter on his/her behalf in a manner that we/I deem fit. We/I encloparty claimant".		nd we/I have full authority to settle
We/l further confirm that we/l will indemnify India International Insurance they will or have already incurred in the event that "the third party of further claim against the former for any loss and expenses suffered per of use pursuant to the damage to FBM9732U (vehicle no.) as a result of the confirmation of the confirmati	laimant" after the ertaining to cost of	above said agreement lodges a
We/I confirm that the agreement reached above is in full and final supursuant to the accident and that further this settlement is reached on a basis.		
This agreement is subject to the application of Singapore law and the Si dispute arising out of the same.	ngapore Courts ha	ve exclusive jurisdiction over any
We/l authorize you to pay the total amount of S\$_1,926.68_to_Ba	n Hock Hin C	Co. Pte Ltd_
Dated thisday of		
CLAIMANT: Signature:	WITNESS: Signature:	(LKK) CKS
Signed by "the workshop" (with chops Tan Teck Hang	Name:	Signed by appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
NRIC: \$ 1438567C	NRIC:	199607198R
Address: 6 Defi Care 4	Address:	51 UBI AVE 1 #02-25
Singapore 539410		PAYA UBI INDUSTRIAL PARK S(408933)
Nationality: Sugsporean	Nationality:	
Occupation: Director	Occupation:	

Occupation:

Merimen e-Claims Page 1 of 1

Print Received Message

This mail is associated with:

*FBM9732U (MCT20060235) [SHB6232C]

BAN HOCK HIN COMPANY PTE LTD
Jun 22 2020 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Ban Hock Hin Co. Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/08/2020 12:34 PM.

To LKK HQ

Subject Alert - Adj Mandate Approved (S\$1956.68) - FBM9732U - Claim Handler: Sherini Pillai



09 JUL 2020

Your Ref

: CC4/III20006691/Uga3

Our Ref

: TP/11569/FBM9732U/SHB6232C

BY FAX & HAND

India International Insurance Pte Ltd 64 Cecil Street #04-00 & 06-00 IOB Building Singapore 049711

ATTN: MS. Cecilia Chong

Dear Cecilia,

Accident Involving FBM9732U & SHB6232C on 22/06/2020

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

 Cost of Repair (Inc 7% GST) 	\$1	,859.23
2. Loss of Use (3 days x \$20)	\$	60.00
3. LTA Vehicle Insurance Search Fee	\$	7.45
TOTAL	\$1	.926.68

We attached our Tax Invoice and LTA Vehicle Insurer Search for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan


Manager/Insurance Dept Tel: 6281 6520 ext. 220

Fax: 6284 2969

Email: raymond@bhh.com.sg









Customer:

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET #04-00 & #06-00 IOB BUILDING SINGAPORE 049711

MOTOR CLAIMS DEPT

CLAIM NO.

: 11569

POLICY NO.

: MC/00804752

VEHICLE NO. MAKE/MODEL : FBM9732U

: YAM / YBR125

TAX INVOICE

GST Reg No.: M2-0010542-7

Invoice No. : LECR20038252-I11569

Invoice Date : 08/07/2020 Payment Due Date : 07/08/2020

(Page 1 of 2)

<u>S/N</u>	Description	<u>Action</u>	<u>Qty</u>	Unit Price	<u>Amount</u>
1	BRACKET FOOTREST RH	REPLACE	1	\$117.00 Disc %: 50%	\$58.50
2	COVER TAIL CENTER	REPLACE	1	\$118.00 Disc %: 10%	\$106.20
3	COVER TAIL LH (RED)	REPLACE	1	\$77.00 Disc %: 10%	\$69.30
4	COVER TAIL RH (RED)	REPLACE	1	\$90.00 Disc %: 10%	\$81.00
5	CRASH BAR	REPLACE	1	\$203.00 Disc %: 10%	\$182.70
6	FOOTREST FRONT	REPLACE	1	\$54.00 Disc %: 10%	\$48.60
7	GASKET EXHAUST PIPE	REPLACE	1	\$6.00 Disc %: 10%	\$5.40
8	LAMP SIGNAL REAR RH	REPLACE	1	\$16.00 Disc %: 10%	\$14.40
9	LEVER BRAKE	REPLACE	1	\$19.00 Disc %: 10%	\$17.10
10	MIRROR RH	REPLACE	1	\$35.00 Disc %: 10%	\$31.50
11	MUDGUARD REAR	REPLACE	1	\$68.00 Disc %: 10%	\$61.20
12	PIPE EXHAUST ASSY	REPLACE		\$1,500.00 Disc %: 50%	\$750.00
13	RUBBER FOOTREST FRONT	REPLACE	1	\$14.00 Disc %: 10%	\$12.60
14	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	REPLACE	1	\$19.00	\$17.10
15	VISOR	REPLACE	1	Disc %: 10% \$30.00 Disc %: 10%	\$27.00
16	TRANSPORT CHARGES		1	\$35.00	\$35.00
17	LABOUR	Supply/Install	1	\$220.00	\$220.00







Invoice No.: LECR20038252-I11569

(Page 2 of 2)

<u>S/N</u>	<u>Description</u>	<u>Action</u>	Qty	Unit Price	<u>Amount</u>
		SUB TOTAL			\$1,737.60
		GST @ 7 %			\$121.63
		GRAND TOTAL (SC	GD)		\$1,859.23
V / 11 11	t 00 d				

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Printed by: RAYMOND







Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

24 Jun 2020 / 17:17:54

Receipt Date/Time :

24 Jun 2020 / 17:17:54

Tax Invoice/Receipt

Receipt No.: ITNET-00000-200624-002904

Previous Receipt No.:

Trovious recoipt no.:				
S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHB6232C As at 22 Jun 2020/12:10:00 Insurance Co: INDIA INT'L INS PTE LTD 1 Insurance Enquiry - SHB6232C Enquiry Fee 20200624171601114352		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20200624171640101	Direct Debit: eN (Internet Ba		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.