



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20006695/Kba3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 14-09-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 3423K	Veh. Inspected	EL 818K
Policy No.	VPA/P2053894	Coverage (\$)	0.00
Claim No.	S0M02PLB	Excess (\$)	0.00
Assign From		Assign Date	25/06/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W.730I (A)	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WBAHL22020DD51519	Colour	METALLIC SILVER
Odometer	120916	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R18	CONTINENTAL	7 mm
L/H Front Tyre	245/50 R18	CONTINENTAL	7 mm
R/H Rear Tyre	245/50 R18	CONTINENTAL	7 mm
L/H Rear Tyre	245/50 R18	CONTINENTAL	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/06/2020	Inspection Date	29/06/2020
Survey held at	LOH HENG BLK 176 #03-08 SIN MING DRIVE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------