

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT
ENGINEERING

R08M1 - LKK Auto

| | |
|---------------------------|---------------|
| ACCIDENT TIME REPORTED | 16:35hrs |
| ACCIDENT DATE | 19-Jun-20 |
| BUS CAPTAIN NAME | WEE HAN CHING |
| THIRD PARTY CLAIM AGAINST | 1st Capital |

| | |
|-------------------------|----------|
| BUS REGISTRATION NUMBER | SBS3333X |
| BUS TYPE (SD/DD) | DD |
| BUS ROUTE NUMBER | |
| BUS ADVERTS (Y/N) | N |

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

| NO. | Part or Item Description | Quantity | Total Cost |
|----------------|---|------------------|-------------------------|
| 1 | O/S/R PANEL LIGHT <i>cm /</i> | 1 | \$996.22 |
| 2 | LAMP REVERSED LED <i>bro /</i> | 1 | \$216.30 |
| 3 | SIKAFLEX BLACK <i>ac /</i> | 1 | \$32.00 |
| 4 | REAR ROUND REFLECTOR VOLVO <i>bn /</i> | 1 | \$9.20 |
| 5 | O/S/R ADVERTISEMENT STICKER <i>na /</i> | * SPECIAL NETT * | 600 \$700.00 |
| 6 | REAR ENGINE DOOR STICKER <i>bt /</i> | 1 | \$800.00 |
| 7 | | | |
| 8 | | | |
| <u>2653.72</u> | | 7% GST | \$192.76 |
| | | PARTS TOTAL COST | \$2,946.48 |

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

| LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT) | TOTAL COST |
|---|--|
| TO DISMANTLE & REPLACE DAMAGED PARTS | 975 \$1,950.00 |
| TO PERFORM REPAIR WORKS ON REAR ENGINE DOOR | \$650.00 |
| TO REMOVE & REPLACE ADVERTISEMENT STICKERS BY CONTRACTOR | * SPECIAL NETT * 300 \$600.00 |
| | |
| | 1925 |
| | |
| | |
| | |
| | |
| | 7% GST |
| | \$224.00 |
| | LABOUR TOTAL COST |
| | \$3,424.00 |

SPRAY PAINTING \$640 PER PANEL
LABOUR CHARGES \$650 PER DAY

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

| | |
|-------------------|--|
| TOTAL TOWING COST | |
|-------------------|--|

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

| | |
|----------------------|------------|
| DATE IN | 26/6/2020 |
| DATE & TIME SURVEY | 26/6/2020 |
| DATE OUT | |
| TOTAL NUMBER OF DAYS | |
| BUS TYPE (SD / DD) | DD |
| LOSS OF USE COST | \$2,000.00 |

| SUMMARY | |
|--------------|-------------------|
| SECTION NO. | COST |
| 1 | \$2,946.48 |
| 2 | \$3,424.00 |
| 3 | - |
| 4 | \$2,000.00 |
| TOTAL | \$8,370.48 |

2653.72
1925.00
4578.72

4 DAYS

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
Hp 90010068
4 days
26/06/2020 @ 1210
Reay after repair
include damage parts