

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 25/06/2020

Address : TAN LEONG SENG
BLK 4 TANJONG PAGAR PLAZA
#16-20
SINGAPORE 081004

Reference : TP 1247/06/20
Vehicle No : SKV 8763H
Make/Model : HONDA VEZEL
Insurance Co. : NTUC

RE : QUOTATION TO SKV 8763H FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>
1) FRONT BUMPER <i>de</i> ✓	1	\$ 927.50
2) FRONT BUMPER RETAINER LH <i>ne</i> ✓	1	\$ 20.60
3) FRONT BUMPER ENFORCEMENT <i>X</i>	1	\$ 321.00
4) FRONT BUMPER BRACKET <i>ne</i> ✓	1	\$ 32.00
5) HEADLAMP LH <i>bro</i> ✓	1	\$ 1,710.50
6) HEADLAMP BRACKET <i>cm</i> ✓	1	\$ 35.20
7) HEADLAMP BALLAST <i>X</i>	1	\$ 780.00
8) FRONT FENDER LH <i>bt</i> ✓	1	\$ 558.70
9) FRONT FENDER LH COWLING <i>de</i> ✓	1	\$ 130.10
10) FRONT BONNET <i>bt</i> ✓	1	\$ 892.35
11) FRONT BONNET UNDER COVER <i>turn</i> ✓	1	\$ 122.30
12) COWLING & BUMPER CLIPS <i>ne</i> ✓	10	\$ 65.50
13) UNDER COVER CLIPS <i>ne X</i>	10	\$ 65.50
14) BONNET HINGES LH <i>bt</i> ✓	1	\$ 48.50
15) BONNET RUBBER <i>ne</i> ✓	4	\$ 150.20
16) WIPER GARNISH <i>X</i>	1	\$ 240.15
17) BATTERY TRAY <i>?</i>	1	\$ 65.00

LIST PRICE TOTAL	\$ 6,165.10
LESS DISCOUNT 20%	\$ 1,233.02
LIST PRICE TOTAL AFTER LESS	\$ 4,932.08

18) BATTERY <i>?</i>	\$ 280.00 200?
----------------------	---------------------------

NETT PRICE TOTAL	\$280.00
------------------	----------

TOTAL PARTS COST

\$5,212.08

LABOUR AND MISCELLANEOUS CHARGES

- | | | |
|----|--|--|
| 1) | TO REMOVE & REPLACE FRONT LH FENDER, BONNET, BUMPER, ENFORCEMENT AND TO PANEL BEAT ALIGN BODY CHASSIS PANEL. | \$ 1,800.00 800
(8 DAYS) |
| 2) | TO PUTTY & SPRAY PAINT FRONT BONNET, FENDER, BUMPER AND OTHER AFFECTED AREA. (PEARL WHITE) | \$ 1,200.00 800
(6 PANELS) |
| 3) | TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP. | \$ 80.00 30 |
| 4) | TUFF KOTE | \$ 250.00 80 |

LABOUR TOTAL

\$ 3,130.00

TOTAL ESTIMATED REPAIR COST

\$ 8,062.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Resul
Ap 90010568
7 days
4/3
29/06/2020 @ 1010
Resurvey after repair