

AM MOTORWERKZ PTE LTD

50 Serangoon North Avenue 4 First Centre #05-10 Singapore 555856

QUOTATION FOR REPAIR : FBQ4082Z

QTY	DESCRIPTION	REPAIRER ESTIMATE			
1	LHS REAR FAIRING (MATTE BLACK) ✓ CUT	\$ 180.00	60		
1	LHS CENTRE PANEL (GLOSS BLACK) ✓ DE	\$ 150.00	✓		
1	LHS FOOT PLATFORM UNDERCOVER ✓ CUT	\$ 150.00	50		
1	LHS FRONT SIGNAL FAIRING (OUTER) ✓ CUT	\$ 150.00	140		
1	RHS FRONT SIGNAL FAIRING (OUTER) ✓ CRA	\$ 150.00	140		
1	FRONT V PANEL ✓ BR	\$ 130.00	90		
1	RHS FOOT PLATFORM UNDERCOVER ✓ CUT	\$ 150.00	50		
1	RHS CENTRE PANEL (GLOSS BLACK) ✓ CUT	\$ 150.00	✓		
1	LHS FRONT SIGNAL FAIRING (INNER) X NN	\$ 150.00	X		
1	RHS FRONT SIGNAL FAIRING (INNER) ✓ CRA	\$ 150.00	65		
1	METER FAIRING COVER (GLOSS BLACK) ✓ CRA	\$ 120.00	60		
1	METER FAIRING COVER (MATTE BLACK) ✓ CRA	\$ 120.00	60		
1	FRONT MUDGUARD ✓ CUT	\$ 120.00	95		
1	FRONT INNER SPLASHGUARD ✓ DE	\$ 180.00	50		
1	EXHAUST COVER X NN	\$ 160.00	50 X		
1	RADIATOR COVER X NN	\$ 180.00	130 X		
1	TAILLIGHT FAIRING (CENTRE PIECE) ✓ BR	\$ 130.00	✓		
1	AIRBOX COVER ✓ CUT	\$ 200.00	✓		
2	REAR SIGNAL LIGHT 1 SET ✓ CUT	\$ 220.00	50		
1	REAR NUMBER PLATE ✓ CUT	\$ 50.00	10(SN)		
2	1 SET SIDE MIRROR ✓ BR	\$ 220.00	30		
2	1 SET BRAKE LEVER ✓ BR	\$ 180.00	24		
2	1 SET BALANCER ✓ CUT	\$ 160.00	30		
1	BREMBO MASTER BRAKE PUMP ✓ DIS	\$ 1,550.00	285		
1	BREMBO MASTER BRAKE RESERVOIR X NN	\$ 180.00	X		
1	BRAKE HOSE LINE ✓ CUT	\$ 320.00	110		
1	FORK SET ✓ BT	\$ 680.00	500		
1	FRONT WHEEL AXLE SHAFT ✓ CUT	\$ 80.00	35		
1	FRONT WHEEL AXLE NUT ✓ CUT	\$ 20.00	✓		
2	1 SET PILLION FOOT REST ✓ CUT	\$ 120.00	75		
1	HANDLEBAR ✓ BT	\$ 180.00	64		
1	BRAKE SWITCH ✓ DM	\$ 120.00	✓		
1	ABS SENSOR FRONT X NN	\$ 450.00	X		
1	FRONT ROTOR ✓ BT	\$ 280.00	150		
1	FORK UNDER BRACKET ✓ BT	\$ 450.00	180		
1	STEERING CONE BEARING ✓ NEC	\$ 360.00	90		
1	HORN ✓ NW	\$ 50.00	✓		
1	RHS FRONT LOWER SIGNAL ✓ CRA	\$ 120.00	38		
1	RADIATOR X NN	\$ 380.00	X		
	HEADLIGHT ✓ CRA \$850	160			
	ECU ✓ DM \$850	450 750	\$ 8,890.00	4481 4881	4751
LESS 10%	METER ✓ CRA \$680	950 500	\$ 889.00		
			\$ 8,001.00	4002.9 4302.9	4275.9
	TOWING FEE	\$ 120.00	50		
	TO DIAGNOSE AND RESET FAULT CODE	\$ 500.00	100		
	LABOUR FEE	\$ 800.00	350 450		
		\$ 1,420.00	600		
	TOTAL REPAIRER ESTIMATE	\$ 9,421.00	4442.9 5002.9	4885.9	

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: