

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/TP/0451/2020/N5

Date

7-Jul-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMN 905 L

Model No

Audi A3 Sedan 1.0 TFSI 8V

| Quantity       | Description                                                                                                                    | Unit Price                  | Amount |
|----------------|--------------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------|
| <b>Parts</b>   |                                                                                                                                |                             |        |
| 1              | Rear end panelling outer <i>Dented.</i>                                                                                        | \$ 339.00                   | ✓      |
| 2              | Acrylic sealant <i>2</i>                                                                                                       | \$ 180.00                   | ✓      |
| 3              | Cavity wax <i>new</i>                                                                                                          | \$ 140.00                   | ✓      |
| 4              | Stone chip                                                                                                                     | \$ 180.00                   | ✓      |
| <b>Labours</b> |                                                                                                                                |                             |        |
| 1              | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. | s/n \$ 480.00               | ✓      |
| 2              | To cut out and weld rear end panelling outer.                                                                                  | \$ <del>2,800.00</del> 1000 |        |
| 3              | To respray rear end panelling outer.                                                                                           | \$ <del>1,000.00</del> 550  |        |
| <b>TOTAL</b>   |                                                                                                                                | <b>\$ 5,119.00</b>          |        |

For Premium Automobiles Pte Ltd

*Adrian Ling*  
*07/07/20*  
*HLG*

Authorised Signature

*Add 2 days of repairs.*