BMW Dealer

# **Performance Motors Limited**

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road Bast Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

29 JUN 2020

## ESTIMATE

Estimate No.  Date Estimated  Prepared By	: b1 55364 : 29/06/2020		Page No.	: 1 of 5
- FOTTMATE DE	: Foong Shiuh Jye	- ACCOUNT -	210	

Singapore 277782	
	Singapore 049711
	#04-05 IOB Building
47 Lily Avenue	64 Cecil Street
Leong Lai Fun Liza	India Int'L Insurance Pte Ltd
- ESTIMATE REPAIR FOR -	- ACCOUNT - 219

SFZ821P	WBAJG120403G76761	29/10/2018	X1 sDrive18i	0
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
ſ				

REGN. NO.	CHASSIS NO.	REGN. DATE	MOI	DEL			MILEA	AGE
SFZ821P	WBAJG120403G76761	29/10/2018	X1	sDrive18	3i		0	
	DESCRIPTION							VALUE
	To replace bumper rear cover, side To repair rear left side panel	sill trim and attachm	ents					3,400.00
	To spray paint bumper rear cover, reand wheelarch trim	ear left side panel						2,292.00
	To check steering geometry and co- according to BMW specification (1X		nt					531.00
	To replace wheel rim left rear include	ling balancing. (1x).						94.00
	To supply tyre.							500.00
	To check electrical wiring systems a rear section for proper function.	and lightings at the						177.00
	Sundries.							80.00
					Tot	al Labour 1:		7,074.00
	DESCRIPTION			<u> </u>	TY_	PRIC		VALUE
	ALLOY RIM 7.5X17 V SPK 560				1	814.00		814.00
	REAR LH BUMPER MOUNT				1	161.40		161.40
	RR BUMPER LH CORNER MOUN	TING			1	142.65		142.65
	REAR BUMPER PANEL PRIMED				1	903.40		903.40
	REAR BUMPER MIDDLE TRIM PA	, ,			1	265.65		265.65
1	FRT LH MOULDING ROCKER PAI				1	79.95		79.95
	REAR LH MOULDING ROCKER P. LH SIDE SKIRT TRIM (BASIS)	ANEL			1	64.55 235.65		64.55
	REAR LH WHEEL ARCH TRIM				1	151.80		235.65 151.80
					Tot	al Parts :		2,819.05

BMW Dealer

## Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



Page No. : 2 of 5

GST REG. NO: M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55364

Date Estimated : 29/06/2020

Prepared By : Foong Shiuh Jye

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

SFZ821P WBAJG120403G76761 29/10/2018 X1 sDrive18i 0

Labour 1 : 7,074.00
Parts : 2,819.05
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 692.51

Grand Total : 10,585.56

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

#### **AXA INSURANCE PTE LTD**

8 Shenton Way, #24-01 AXA Tower, Singapore 068811 Customer Centre #01-21 Tel:1800 8804888 Website:www.axa.com.sg GST Registration Number: 199903512M customer.care@axa.com.sg



Agent Code: 14235

Policy No.(if any):

**New Business** 

Original

SmartDrive Quote Ref:

### MOTOR COVER NOTE

No. CN018231

- e The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;

• And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

#### SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD		
INSURED	LEONG LAI FUN LIZA		
MAKE AND DESCRIPTION OF VEHICLE	BMW X1 SDRIVE 18I RL		
VEHICLE REGISTRATION NO.	SFZ821P		
YEAR OF MANUFACTURE	2018		
ENGINE NO.	38245458B38B15A		
CHASSIS NO.	WBAJG120403G76761		
ENGINE CAPACITY/TONNAGE	1499		
COVER TYPE	COMPREHENSIVE		
HIRE PURCHASE	DBS BANK LTD		
VALUE (S\$)	AS PER MARKET VALUE		
PERIOD OF INSURANCE	FROM: 29/10/2018 TO: 28/10/2020		
EXCESS (S\$)	\$600		
AXA PREMIUM WORKSHOP?	NO ·		

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).



Issued by SD CONTEGO SERVICES on 19/10/2018 9:21 am

AXA INSURANCE PTE LTD

Authorised Signature

**Note:** This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of \$\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged :
  - Cover note issued and cancelled before inception.
  - Retaining the old registration number for a new vehicle insuring with AXA.

#### PREMIUM WARRANTY

For Individual Customers:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid. For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

MTR/C/NOTE/V01/03