

**HWA SENG SPRAY PAINTING CO**  
 160 Sin Ming Drive  
 #05-11 Sin Ming Autocity  
 SINGAPORE 575722  
 (COMPANY REGISTRATION NO. 09574400B)  
 TEL : 64533100  
 FAX : 62669932

Date of accident : 25/06/2020

Your Insured SCW 230 X


**ESTIMATE REPAIR COST TO MERCEDES BENZ E200 REG. NO. : SLX 2278 J**

		S\$
1pc	Front Bumper	Buckler 1650.00 ✓
1pc	Front Bumper Right Retainer	in 95.00 X
1pc	O/S/F Sensor	Sun 285.00 ✓
1pc	Right Headlamp	in 3900.00 X
		5930.00
Less : 10%		593.00
		5337.00

**LABOUR & MISC CHARGES**

Panel Knocking	380.00	2501
Spray Painting	480.00	3001
Wire Checking & Programming Headlamp	160.00	201
Computerised Wheel Alignment	150.00	X
		6507.00
<b>TOTAL</b>		

**HWA SENG SPRAY PAINTING COMPANY**



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

NOT WITHIN  
 61 Day 8?  
 Resurvey After Paint  
 2 days

LKK - Summer  
 6741.8434