

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1123G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT O/S HEAD LAMP	NOT NECESSARY	1,531.57	-
1	FRONT BUMPER	DEFORMED	811.11	811.11
1	FRONT BUMPER EMBLEM	NOT NECESSARY	27.80	-
1	FRONT BUMPER O/S SIDE BRACKET	BROKEN	32.51	32.51
1	FRONT BUMPER O/S UPPER BRACKET	NOT NECESSARY	92.60	-
1	FRONT BUMPER O/S SUPPORT BRACKET	NOT NECESSARY	37.01	-
1	FRONT O/S FENDER	DENTED	514.02	514.02
1	FRONT O/S FENDER INNER SHIELD	CUT	176.72	176.72
	LESS 20% DISCOUNT		-644.67	-306.87
			2,578.67	1,227.49
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	FRONT O/S FENDER STICKER (SN)	NECESSARY	30.00	20.00
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	15.00
1	SUNDRY (SN)	NECESSARY	50.00	30.00
			156.00	95.00
	LABOUR			
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO FOCUS / CHECK FRONT N/S & O/S HEAD LAMPS.	NOT NECESSARY	60.00	-
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME.		600.00	350.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT O/S FENDER.		400.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	30.00
			1,400.00	780.00
	GRAND TOTAL		4,134.67	2,102.49

Report Ref No. CS/UOI20006833/Esf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/UOI20006833/Esf3e2



**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.