

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 02 Jul 2020

Preliminary Advice

Insured Vehicle No	:	YP7989X		
TP Vehicle No	:	SHA1746A	Accident Date	: 30/06/2020
Make	:	HYUNDAI I40	Assignment Date	: 01/07/2020
Date of Inspection	:	01/07/2020	Est. Duration of Repair	: 2
Inspection At	:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained damages at the n/s portion.

Repairer's Estimate (Gross)	:	S\$ 1,222.00
Revised Amount	:	S\$ 992.00
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 992.00
Lump Sum Repair		:

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :