



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: AC.2018.087

Date: 09th July 2020

Our Ref: CS1/LAW20006903/Gqf3s2

M/s Chey LLC

20 Havelock Road #02-47
Central Square
Singapore 059765

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SDM 12A INSURED VEHICLE: SKE 9073Z ACCIDENT DATE: 20/02/2018**

We thank you for your instruction on 02/07/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDM 12A from M/s Raleigh Services.
- b) Survey report by Auto Performance Appraisal with colour photographs.
- c) Singapore Accident Statement of Vehicles SDM 12A and SKE 9073Z.
- d) Colour damaged vehicle photographs of SDM 12A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDM 12A
Make & Model	: Volkswagen Golf 1.2 TSI
Year of Registration	: 2017
Chassis Number	: WVVZZZAUZGW277658
Engine Capacity	: 1197 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.