



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. AC2004887
INV Date 13/07/2020
Reference CS3/III20006910/Etf3e2
Code III2



PROFESSIONAL SERVICE FEE

Vehicle No. SKU 6131A

Insured Veh. SHC 8871P

Claim No.

Policy No.

Accident Date 30/06/2020

Inspection Date 06/07/2020

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 06.07.2020 11.00am	
- Dismantle Inspection 07.07.2020 11.54am	
- After Repair Inspection 08.07.2020 04.32pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM