

Our Ref : OD/072020/4448
Accident date: 30/6/2020
Your Ref : DMPCSN1936211900

Tax Invoice :

Date : 9/9/2020

MOTOR CLAIM DEPARTMENT
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

SUPPLEMENTARY COST OF REPAIRS

Model : JAGUAR XJ 3.0
Vehicle No. : SDX68G

Climate Control
Adaptive Dynamic Fault
Suspension Fault
Car clock is not correct
RPM @ N mode, vehicle is shaking
The screen is blurry with moisture (centre)
Sun roof cover is not working

VIN'S MOTOR PTE LTD

